



VOLKSWAGEN GOLF: GM-086-JH

Vinnumber:	WVWZZZCD4PW022171	Versionname:	VOLKSWAGEN GOLF 1.0 eTSI OPF 110 DSG7 Life Business VP [5P] bva 7-110CH-6cv (bi-corps)
First Registrationdate:	24/02/2023	Fiscalpower:	
Expertise Mileage:	80799	Power Kw:	81
Bodytype:	Berline	Body colour:	Grey
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Petrol	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Radio	
Number keys remote	2	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Rear view camera	
Steering wheel leather		Seat cover lining	Lining Other
Type of climate control	Autom climate control		

Tyres

	205/55/16/94 V			
Summer tyres:	Fr.L.	Michelin: 45%	Fr.R.	Michelin: 45%
	Re.L.	Nexen: 55%	Re.R.	Nexen: 50%
Tyre profile depth FL	5.4			
Tyre profile depth FR	5.3			
Tyre profile depth RL	4.7			
Tyre profile depth RR	4.8			
Tyre size FL	205/55 R 16 94 V			
Tyre size FR	205/55 R 16 94 V			
Tyre size RL	205/55 R 16 91 V			
Tyre size RR	205/55 R 16 91 V			
Tyre type FL	Summer			
Tyre type FR	Summer			
Tyre type RL	Summer			
Tyre type RR	Summer			
Tyre make FL	261			
Tyre make FR	261			
Tyre make RL	1957072			
Tyre make RR	1957072			

Assistance equipment


Emergency spare wheel	Yes	Runflat	No
Interior, Stain, Cleaning			



Alloy rim FL, Scratch(es), Repair/replace (lump sum)



Alloy rim FR, Scratch(es), Repair/replace (lump sum)




Outside rear-view mirror housing L, Scratch(es), Paint



Door RL, Scratch(es), Polish



Door RR, Dent(s), Repair and paint (complete)



Historique Maintenance

Immatriculation: **GM-086-JH**

Date de 1ère immatriculation: **24/02/2023**

Modèle: **Volkswagen GOLF 1.0 eTSI OPF 110 DSG7 Life Business VP [5P] bva 7-110CH-6cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
28/03/2025	59.682	SELECTION AUTO	REVISION
	0		BALAIS ESSUIE GLACE AV
	0		BALAI ESSUIE GLACE AR
03/06/2024	30.954	VELIZY AUTOMOBILES	BALAI ESSUIE GLACE AR
	0		LIQUIDE LAVE GLACE
	0		PILE DE CLE RPLT
	0		REVISION
	0		PLAQUETTES AV RPLT
	0		PLAQUETTES AR RPLT
	0		LIQUIDE DE FREIN
	0		FILTRE CLIM RPLT
	0		BALAIS ESSUIE GLACE AV