



CITROËN BERLINGO: FM-286-RG

Vinnumber:	VR7EFYHYCKJ812052	Versionname:	CITROËN BERLINGO M 650kg BlueHDi 100 BVM Driver VU [4P] bvm 5-100CH-5cv (fourgonnettesimple cabine)
First Registrationdate:	26/12/2019	Fiscalpower:	
Expertise Mileage:	101243	Power Kw:	73
Bodytype:	Transporter	Body colour:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Steel
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Type of rims (mounted):	Steel		
Category:	Light Commercial Vehicle		

Options

Number of keys total	1	Radio	
Number keys remote	1	Front parking sensors	
GPS big screen color		Rear parking sensors	
Windows electric F		Sliding door right-side	
Cruise Control		Rear view camera	
Steering wheel multifunctional		Seat cover lining	Lining Other
Type of climate control	Manual climate control		

Tyres

	195/65/15/95 V			
Summer tyres:	Fr.L.	Michelin: 35%	Fr.R.	Michelin: 30%
	Re.L.	Michelin: 25%	Re.R.	Michelin: 30%
Tyre profile depth FL				6.0
Tyre profile depth FR				6.2
Tyre profile depth RL				6.6
Tyre profile depth RR				6.2
Tyre size FL				195/65 R 15 95 V
Tyre size FR				195/65 R 15 95 V
Tyre size RL				195/65 R 15 95 V
Tyre size RR				195/65 R 15 95 V
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Remote ignition key, Missing, Repair/replace (lump sum)



Malfunction indicator, Blinking, Check



Interior, Dirty, Cleaning



Side wall RL, Scratch(es), Polish



Door FL, Scratch(es), Paint



Windscreen, Crack, Replace



Windscreen glue kit, Required to install glazing, Repair/replace (lump sum)



Bonnet, Scratch(es), Polish



Outer sill R, Dent(s) and scratch(es), Repair and paint (complete)



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Side wall RR, Dent(s), Acceptable



Bumper corner RL, Bad repair, Replace



Bumper R, Scratch(es), Acceptable



Boot door panel RR, Scratch(es), Paint



Boot door panel RL, Dent(s) and scratch(es), Repair and paint (complete)



Bodywork, Glue residues, Sticker removal small



Historique Maintenance

Immatriculation: **FM-286-RG** Date de 1ère immatriculation: **26/12/2019**

Modèle: **Citroen BERLINGO M 650kg BlueHDi 100 BVM Driver VU [4P] bvm 5-100CH-5cv (fourgonnettesimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
05/03/2026	97.518	SOGAMA SOCIETE DU GRAND GARAGE DE MAUBEUGE	POT CATALYTIQUE FAP RPLT
	0		INJECTEURS RPLT
	0		DIAG
07/01/2026	95.149	SOGAMA SOCIETE DU GRAND GARAGE DE MAUBEUGE	DIVERS ECHAPPEMENT
	0		ADBLUE
27/05/2025	85.851	GARAGE VAUBAN	PLAQUETTES AR RPLT
	0		DIAG
	0		BALAIS ESSUIE GLACE AV
	0		REVISION
	0		ADBLUE
	0		FILTRE CLIM RPLT
	0		LIQUIDE DE FREIN
13/05/2025	85.482	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
24/04/2024	72.453	CONTITRADE FRANCE	REMPLACEMENT PNEUS 4 SAISONS
28/03/2024	70.429	SOVALDIA SOCIETE VALENCIENNOISE DE DISTRIBUTION AUTOMOBILES	REVISION
	0		DIVERS ECHAPPEMENT
	0		DISQUES PLAQUETTES AV RPLT
	0		REVISION
	0		FILTRE CLIM RPLT
	0		FILTRE A AIR RPLT
27/02/2024	68.359	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
01/03/2023	57.097	EUROMASTER FRANCE	REPARATION DE ROUE
03/06/2022	30.220	EUROMASTER FRANCE	REMPLACEMENT PNEUS ETE
23/12/2021	20.267	GARAGE VAUBAN	REVISION ET CLIM
	0		ADBLUE
	0		BALAIS ESSUIE GLACE AV
	0		LIQUIDE DE FREIN