

» Overview

Order number: 1002407471
Order completed: 17.04.2026 13:06
Report number: 10445740
VIN: WVVZZZCD0RW177366



Front Left 3/4



Rear Right 3/4



Mileage

» Vehicle Data

Vehicle category:	Passenger Car
Vehicle type:	Limousine
Make:	Volkswagen
Model:	Golf
Manufacturers and type code:	0603 / CMI
Date of first registration:	12.03.2024
Mileage:	29,198 km
Proof of mileage:	ReadOff
Exterior colour:	Pure White
Roof colour:	Pure White
Propulsion:	Front
Fuel:	Petrol
Engine size (cc):	2,000 ccm
Performance:	180 kW (245 PS)
Length:	
Height:	
Width:	
Permitted total weight:	
Wheelbase:	
Number of powered axles:	2
Cylinders:	4
Euronorm:	Euro 6
Number of doors:	5
Number of seats:	5
Gearbox:	Manual 6-speed
Upholstery type:	Lining fabrics
Interior colour:	Soul-Schwarz - Tornadorot/Soul-Schwarz/ Schwarz/Soul-Schwarz
Number of keys:	2

» Documents & Maintenance

Statutory inspection date:	03.2027
Registration certificate available:	Yes
Registration certificate received:	Yes
License plate:	Both
Maintenance book:	Digital
Maintenance:	Not testable
Maintenance last date:	
Maintenance last mileage:	

"DRIVER ALERT" - driver alert system	Driving on the right
12-V outlet in luggage compartment	Dynamic headlight range control
2 LED reading lights in front and 2 in rear	Electromechanical parking brake with Auto Hold function
2 USB-C ports in the front, 2 USB-C charging sockets on the center console in rear, charging capacity up to 45 W	Electronic immobilizer
3 head restraints in rear	Electronic restriction of top speed
30-color ambient lighting, illuminated center console storage compartment in front	Electronic Stability Control and electromechanical brake booster
3-point seat belts for the outer rear seats	Emergency call service, 10-year contract duration as of initial delivery, condition: mob. phone network available
3-point seat belts in front with height adjustment and seat belt pretensioners	Emission standard EU6 AP
4 alloy wheels "Richmond" 7.5J x 17	Equipment options subset for Germany
4-cylinder SI engine 2.0 l	Ext. mirrors, power-adjustable and heated, with memory feature and front passenger ext. mirror lowering function
4-cylinder SI engine 2.0 l TSI, 180 kW	Extended pedestrian protection
6+1 speakers	Exterior mirrors: aspherical on driver side, convex on front passenger side
6-speed manual transmission	First aid kit, warning triangle and safety vest
Activated carbon canister (Evaporative Emission Control System (EVAP))	Four-link suspension
Air Care Climatronic 3 zone automatic climate control w/ allergen filter, enhanced air filter a. controls in rear	Front center armrest, height- and longitudinally adjustable
Alternator 140 A	Front differential lock
App-Connect Wireless for Apple CarPlay and Android Auto	Front head restraints integrated into the seat
Auto. Emergency Braking Front Assist with Pedestrian and Cyclist Monitoring	Front seats with height adjustment
Automatic headlight control with LED separate daytime running light and entry and exit lighting	Front stabilizer bar
Basic equipment variant	Front-wheel drive
Battery 420 A (70 Ah)	Fuel system for fuel-injected SI engine
Body-colored bumpers, air intake in honeycomb structure	Gearshift knob/handle in aluminum
Body-colored exterior mirror housings and door handles	Green heat-insulating glass windows on sides and in rear
Car2X	Hatchback
Carpet mats in front and rear	Headliner
Chrome elements on power mirror and window regulator switches, chrome trims on the vents	Illuminated molding between headlamps and illuminated door handle recesses
Cornering light and poor weather light	Illuminated vanity mirrors in sun visors
Curtain airbags in front and rear, side airbags in front, center airbag	Initial standard fuel filling
Decorative inserts "Black Metal Chrome" for dashboard and front door trim panels	Inserts of front seats and outer rear seats in fabric "Scale Paper"
Delivery "Autostadt Wolfsburg"	Instrument cluster with electronic speedometer, odometer and trip odometer, tachometer
Digital radio reception DAB+	ISOFIX anchors for child seats on outer rear bench seats and on front passenger seat, compatible for i-Size
Dimming interior rearview mirror	Keyless Start without SAFELOCK
Disc brakes in front	Laminated safety glass windshield, heat- and sound-insulating
Disc brakes in rear	Lane keeping system Lane Assist
Diversity antenna for FM reception	Leather-wrapped multi-function sports steering wheel with touch control
Door and side trim panel	LED light unit in front footwell, selectable light color
Driver and front passenger airbag with front passenger airbag deactivation	LED Plus headlamps
Driving Mode Selection	LED rear combination lamps

Left-hand drive	Standard engine starter
LongLife Service Regime	Standard manufacturing sequence
Lumbar supports in front	Standard paint coating
Manual in German (Germany)	Standard rear seat release
Manual transmission MQ350	Standard roof
Mobile phone interface with inductive charging feature	Start-stop system with regenerative braking
Multi-color Digital Cockpit Pro, selection of different info profiles possible	Surround lighting with welcome light
Multifunction camera	Suspension range 38 installation control only, no requirement forecast
Nameplate set "GTI"	Tailgate/trunk lid unlocking from outside
No special edition	Tire Mobility Set: 12-volt compressor and tire sealant
No special purpose vehicle, standard equipment	Tire Pressure Monitoring System
Non-folding front passenger seat backrest	Tires 225/45 R17 with sporty vehicle dynamics
Non-smoker's package: Storage compartment and 12-V outlet in front	Tool kit
Not hot country	Top sports equipment
Oncoming vehicle braking when turning and swerve support	Transport protection film (minimum protection) with additional transport protection measures
Online service, with OCU, with head unit coding, without engine immobilizer interconnection	Two-tone horn
Operating permit, alteration	Type approval country Germany
Operating voltage 12 V	Unsplit rear bench seat, asymmetric split folding backrest, with center armrest
Park Distance Control - warning signals for obstacles in the front and rear	UWB-capable country and carrier frequency, 433.92 to 434.42 MHz
Part set without country-specific prescriptive standard	Vehicle class differentiation -5H0-
Pedals in brushed stainless steel	Vehicles without special upgrade measures
Premium sports seats in front	Warning signal and warning light for front and rear seat belts not fastened
Preparation for subsequent activation: Navigation feature "Discover Media" incl. Streaming & Internet	Weight range 3 installation control only, no requirement forecast
Preparation for We Connect and We Connect Plus or VW Connect and VW Connect Plus	Wheel locks with extended theft protection
Progressive steering	Wheelbase
Radio	Windshield wiper intermittent control with light sensor
Rear exhaust tailpipe (standard)	Without additional decorative trims
Rear floor panel module, type 1	Without additional front underbody guard
Rear fog light on one side, back-up light on both sides	Without additional tires
Rear stabilizer bar	Without alcohol interlock
Refrigerant R1234yf	Without alternative drive system
Regional code " ECE " for radio	Without auxiliary heater/parking heater
Service indicator 30 000 km or 2 years (variable)	Without camera systems/accident sensors
Shock absorption in front	Without charging cable
Special identification label (EU)	Without decals and emblems
Speed limiter in combination with online services	Without dynamic road sign display
Sports suspension	Without electric motor (hybrid)
Standard battery/alternator capacity	Without extended safety system
Standard climatic zones	Without fire extinguisher
Standard curb weight range	Without headlamp washer system, without washer fluid level indicator
Standard electronic engine sound	Without head-up display

Without heat accumulator/auxiliary heater
Without heated washer nozzles
Without hill start assist/hill descent control/comfort driving assist
Without lane change assist
Without light control
Without locking and starting systems
Without mode 3 charging cable
Without partition
Without preparation for rotating beacon/siren combination
Without preparation for two-way radio installation
Without roof rails
Without seat heater
Without seat ventilation/massage seat
Without second battery
Without special body measures
Without speed limiter
Without trailer hitch
Without UN-ECE cybersecurity & software update
Without voice control

» Tyres

MOUNTED TYRES

Make	Location	Position	Type	Rim	Dimensions	Profile depth
Bridgestone	Front	Left	Summer	Aluminium	225/45 R 17 91 W	5.0 mm
Bridgestone	Front	Right	Summer	Aluminium	225/45 R 17 91 W	5.0 mm
Bridgestone	Rear	Left	Summer	Aluminium	225/45 R 17 91 W	5.0 mm
Bridgestone	Rear	Right	Summer	Aluminium	225/45 R 17 91 W	5.0 mm

Permitted: Yes

Roadworthy: Yes

SPARE/EMERGENCY TYRE & ACCESSORIES

Toolkit present: Yes

Repair kit present: Yes

Repair kit expiration date: 11.2027

Compressor present: Yes

No devaluation factors available

» Usage Damages

Nr	Location	Damage type	Repair type
1	Steering wheel	Scratch(es)	Acceptable
2	Roof	Dent(s)	Acceptable

» Commercial devaluation

Known previous damages:	Yes
Previous damages detectable:	No
Repainting present:	No
Paint thickness measurement performed:	Yes - no abnormalities/deviations

Nr	Location	Damage	Repair type	Repair cost
1	Other	Liability loss		€ 2,000.00
Total without VAT:				€ 2,000.00

PAINTTHICKNESS MEASUREMENT RESULTS

The measured values were in the usual range.

At least 3 measurements were carried out per component.

» Notes On The Assessment

Details of the assignment and the scope of the assessment:

The order was placed to prepare a condition report on the described vehicle.

The vehicle condition assessment was carried out in accordance with the order on the basis of the standards for vehicle assessments specified by the client. The expert makes the findings in the individual case on the basis of his own expertise and at his own expert discretion.

Vehicle identification:

WVWZZZCD0RW177366

VIN checked and matches documentation

Vehicle condition:

Well maintained general condition

Inspection condition:

Insufficient

Lifting platform/lifting equipment used:

Yes

Testdrive carried out:

No

Engine test carried out:

Yes

» **Remarks**

This copy was generated electronically. It is valid without an original signature.

» Commercial Pictures



Front Left 3/4



Front Right 3/4



Rear Left 3/4



Rear Right 3/4



Mileage



Tools



Sill outer L



Sill outer R



Chassis nr



Wheel FL



Wheel FR



Wheel RL



Wheel RR



Central console




Engine compartment



Documents



Interior arrangement



Registration Certificate



History Maintenance



Interior - front



Interior - rear



Tirefit expiration date



GPS/Radio

» Devaluation Damages

USAGE DAMAGES

1 - Steering wheel - Scratch(es) - Acceptable



2 - Roof - Dent(s) - Acceptable

