


2-FXL-858

2-FXL-858 · Cross 1.8 Hybrid Safety Pack DYNAMIC 1.8 140PS AT / · 28 July 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FXL-858	Fuel Type	Hybrid Gasoline
Manufacturer	TOYOTA	VIN	JTNADADB40J020509
Model	Corolla	Cylinder Capacity	1.798 ^{cm3}
Model Versions	Cross 1.8 Hybrid Safety Pack DYNAMIC 1.8 140PS AT /	Transmission Type	Automatisch geschakelde Transmissie
		First Admission	26-09-2024
Body Type	5 door hatchback	Odometer	62.723 ^{Km}
Color	Blue	Numer Of Keys	2
Paint Type	Metallic	Interior	Grey
Production Year	2024	Number Headrests	5
KW	103		

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Fog lights

Leather steering wheel

Navigation system

Rear parking sensors

Rear view camera

Roller cover / parcel shelf

Steering wheel multifunction

Condition

Condition exterior

Adequate

Condition interior

Adequate

Last Maintenance Unknown

Maintenance Remarks Olie verversen

Previous Repairs

Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	3 ^{mm}	Uniroyal	215 ^{mm}	60 ^{mm}	17 ^{inch}	All Season
Rear Left	5 ^{mm}	Uniroyal	215 ^{mm}	60 ^{mm}	17 ^{inch}	All Season
Front Right	3 ^{mm}	Uniroyal	215 ^{mm}	60 ^{mm}	17 ^{inch}	All Season
Rear Right	5 ^{mm}	Uniroyal	215 ^{mm}	60 ^{mm}	17 ^{inch}	All Season
Spare Tire Type	Homecomer					

Damages



Damage Part

Windscreen - Front



Damage Type

Chipped

Repair Type

Window Repair

Acceptable

No



Damage Part

Dashboard



Damage Type

Scratch(es)

Repair Type

Cloth Repair

Acceptable

No



Damage Part

Co drivers seat



Damage Type

Burned

Repair Type

Cloth Repair

Acceptable

No



Damage Part	Damage Type	Repair Type	Acceptable
Drivers seat	Stains & dirt	Cleaning	No



Damage Part	Damage Type	Repair Type	Acceptable
Reardoor - Right	Small dent(s)	Restyle	No



Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor - Right	Small dent(s)	Restyle	No




Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Front	Scratch(es)	Plastic Repair	No



Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Left	Dent(s) & Scratch(es)	Panelbeating & Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Left	Scratch(es)	Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Left	Small dent(s)	Restyle	No



Damage Part

Tailgate



Damage Type

Previous Repair



Repair Type

Spray

Acceptable

No



Damage Part

Bumper - Rear



Damage Type

Scratch(es)



Notes

Middenstuk

Repair
Type

Plastic
Repair


Acceptable

No



Damage Part

Bumper - Rear



Damage Type

Small scratch(es)

Repair Type

Acceptable

Acceptable

Yes