MACADAM








RENAULT Megane: 3432-MGY

Vinnumber:	**VF1RFB00370678249**	Versionname:	**S.T. Equilibre TCe 103 kW (140CV) GPF familiar 103kW 5P manual**
First Registrationdate:	**23/05/2023**	Fiscalpower:	
Expertise Mileage:	**136280**	Power Kw:	
Bodytype:	**Berline**	Body colour	**Red**
Gearbox:	**MAN 6 VIT**	Type of rims (mounted)	**Steel**
Transmission:			
Fueltype:	**Diesel**		
Engine functioning	**Yes**		
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Steel**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**No**		

Options

Number of keys total	**2**	Luggage cover	
Number keys remote	**2**	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Steering wheel leather			
Radio multimedia			
Type of climate control	**Manual climate control**		

Tyres

Summer tyres:	**205/55/16/91 V**			
	Fr.L.	**Goodyear: 7 mm**	Fr.R.	**Goodyear: 7 mm**
	Re.L.	**Goodyear: 5 mm**	Re.R.	**Goodyear: 5 mm**

Tyre profile depth FL	**7.0**
Tyre profile depth FR	**7.0**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**5.0**
Tyre size FL	**205/55 R 16 91 V**
Tyre size FR	**205/55 R 16 91 V**
Tyre size RL	**205/55 R 16 91 V**
Tyre size RR	**205/55 R 16 91 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**259**
Tyre make FR	**259**
Tyre make RL	**259**
Tyre make RR	**259**

Assistance equipment

Repair kit	**Yes**

Registration document, Missing, Repair/replace (lump sum)




Boot lid covering R, Scratch(es), Replace




Wing RL, Dent(s), Repair and paint (complete)




Door FL, Scratch(es), Repair and paint (complete)




Bumper F, Deformed / Strained, Repair and paint (complete)




Wing FR, Scratch(es), Repair and paint (complete)




Bumper R, Scratch(es), Repair and paint (complete)




Internal boot lining L, Broken, Replace




Internal boot lining R, Broken, Replace




Tyres, No damage, Check







ALPHABET

Datos del vehículo

Marca	RENAULT	Matrícula	3432-MGY
Modelo	Mégane	VIN	VF1RFB00370678249
Versión	S.T. Equilibre TCe 103 kW (140CV) GPF familiar 103kW 5P manual		

Histórico

Fecha	Descripción	Kilómetros	Taller
05/03/2024	Rev. 30.000 kms, Rev. Niveles	30643	RNO BYMYCAR BARCELONA S.L.
09/07/2024	Alineado, Sustitución	47267	SERVIGRUP - PNEUMATICS REIXAC, S.A.
03/10/2024	Bujias, Rev. 60.000 kms	61853	REBOLLO HERMANOS S.A.
08/04/2025	Pastillas delanteras, Rev. 90.000 kms, Rev. Niveles	91822	RNO BYMYCAR BARCELONA S.L.
19/01/2026	Aceite motor - - - APL 13, Arandela / tapón cárter, Bujía, Escobilla limpialuna tr, Filtro aceite - Nueva, Filtro aire, Filtro antipolen - CARBON ACTIVO - Nueva, Líquido frenos - DOT4 OEM1 - Nueva, Líquido lavaparabrisas, Serv inspección 120000 KM, Sustituir Bujía, Sustituir Escobilla limpialuna tr, Sustituir Filtro aire, Sustituir Filtro antipolen, Sustituir Líquido frenos, Sustituir Líquido lavaparabrisas, Tasa de gestión de aceites usados	121752	AUTOCARPE CONCESIONARIO, S.L.
17/04/2026	Ecotasa - N2, Goodyear / 542449 205/55X16 GYEAR.EFIG.PERF2 91V, Sustitucion y kit de montaje	133257	F. TOME (GUADALAJARA)

Fecha	Descripción	Kilómetros	Taller