

MACADAM ITALY S.R.L. Piazza Belgioioso, 2 - 20121 Milano (MI) Tel. - Fax Piva: 12729790969				Report No.		Expert's report for Alphabet Italia				Type of insurance Perizia											
				Policyholder				Opposite party				Opposite party company									
				Operation 2026		Claim number				Code / Agency				Date accident 29/06/2026							
				Expert code		Adjuster code				Policy number				Injured person can recover the VAT							
Date assignment 29/06/2026		Date first survey 07/07/2026		Place LUCCA		C/O		Repairs		Photo		Lien in favor of		Expiry date							
Ownership certificate Alphabet Italia - Via Romano Guardini 24 38121 Trento (TN)														Formerly plate							
Lessee / Co-owner														Date of overhaul							
Vehicle (Brand - Model - Version) OPEL CROSSLAND 1.5 Diesel 120cv Ultimate S&S AT6								Plate GG744JJ		Vin Chassis W0V7H9EJ1M4210785				First Registration 20/07/2021							
Usage status NON CONOSCIUTO		Km 76512		Tyres % 30		Color BIANCO		Type of enamel METALLIZED/DOUBLE				Consistency of damage		Type of Expert's report NOT DEFINITIVE							
Equipment																					
Approval code		For commercial vehicles		Carrying Qls 0		Tare, Q 0										Wheelbase		Seats No. 0		Axles 0	
Commercial value (C)		Wrecked car value		Value by difference		Ancillary expenses															
Damaged items / restoration operations								SR		LA		VE		ME		D.M. S.C.		Costs of spare parts			
								Dif Time		Dif Time		Dif Time		Time				* (VAT excluded)			
1		13482345		Front wheel arch trim				R		S		S		S							
1		39157470		Rear bumper lower part						S		S		S							
1		39225256		Trim of rear bumper						S		S		S							
1		39094072		Cover for front seat cushion				L		S		S		S							
1		39203285		rear mudguard				R		M				M							
1		39235944		Front bumper upper part						M				M							
1		39203284		rear mudguard				L		M		M		M							
1		39097387		Rear bumper upper part				L		M				M							
1		39097388		Rear bumper upper part				R		M				M							
1		39228887		Rear hatch						M				M							
1		39111499		External rear-view mirror cap				R						M							
1		Codice Ricambio		Disco in lega da 17 ant.				R													
1		Codice Ricambio		Disco in lega da 17 ant.				L													
1		Codice Ricambio		Mod. lat. paraurti ant. - PRM				R													

New for old value (N)	Remarks Pneum. 215/50 R17 - ant. Kumho, post. Bridgestone. Vhl sporco.
-----------------------	--

ALPHABET

Telaio W0V7H9EJ1M4210785

GG744JJ

OPEL CROSSLAND 1.5 Diesel 120cv Ultimate S&S AT6 sports utility vehicle 120CV 5P automatico

Current Odo (Time of Ma	Maintenance Request	Service Type Descriptio	Maintenance Job Description
10	20/02/23	Maintenance	Presa E Consegna A Domicilio + diagnosi
10	13/04/23	Maintenance	Filtro di antipolline
10	13/04/23	Maintenance	Filtro Olio
10	13/04/23	Maintenance	GENERICO
10	13/04/23	Maintenance	Olio Motore
35.809	12/10/23	Tagliando a 40 000 km	Tagliando a 40 000 km
45.080	15/04/24	Maintenance	Additivo FAP
49.912	04/11/24	Tagliando a 50 000 km	***Service at 50 000 km
61.118	29/07/25	Maintenance	Revisione Periodica MTC
66.040	10/11/25	Tagliando a 70 000 km	***Service at 70 000 km