

Vehicle details

VIN	YSM4ZPAA5 SF427640	Registration date	11/09/2025	Exterior Color	
Brand	Polestar	Licence Plate	N/A	Odometer	14 876 km
Model	POLESTAR 4 LRDM Base (PA / 200 kW (272 PS))	Condition of the car	Mit Schaden		
Pre-damage		Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc.					
					
					
					
					


Removable element

Spare wheel kit	✓
Toolkit	✓
Triangle	✓
Rear parcel shelf	✓
Floor mat BR	✓
Floor mat BL	✓
Floor mat FR	✓
Floor mat FL	✓

Technical Document

User manual	✓
Warranty booklet	✓
Log books	✓
First aid kit	✓
Inspektion	✓
Ladekabel Starkstrom-Steckdose	✓

Tyres



Exterior

DEKRA Automotive Solutions

1		Part	Sticker removal	Repair Time	1.00	Part Cost	-
		Position	-	Repair Cost	77.00€	Net Cost	77.00€
		Damages	Lumpsum	Paint Time	-		
		Comments	-	Paint cost	-		
				Flat Rate	77.00€		
2		Part	Tailgate / Boot door	Repair Time	0.60	Part Cost	-
		Position	-	Repair Cost	46.20€	Net Cost	46.20€
		Damages	Dented - Smart repair	Paint Time	-		
		Comments	-	Paint cost	-		
				Flat Rate	46.20€		
3		Part	Door	Repair Time	0.60	Part Cost	-
		Position	Front left	Repair Cost	46.20€	Net Cost	46.20€
		Damages	Dented - Smart repair	Paint Time	-		
		Comments	-	Paint cost	-		
				Flat Rate	46.20€		

Estimated repair cost

Total	169.40€
--------------	----------------