



Mercedes CLA-Klasse (KKL): 2AQM010

Vinnumber:	W1K1183841N234348	Versionname:	CLA180 Sedan 1.3i 136pk/cv 4p
First Registrationdate:	11/06/2021	Fiscalpower:	
Expertise Mileage:	73900	Power Kw:	100
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:	Petrol		
Maintenance	NOT OK		
Maintenance	ass A min 36 d		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Type of Tow bar	Tow bar collapsible
GPS			
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	225/45/18/95 V			
Winter tyres:	Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 7 mm	Re.R.	Goodyear: 7 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				5.0
Tyre profile depth RL				7.0
Tyre profile depth RR				7.0
Tyre size FL				225/45 R 18 95 V
Tyre size FR				225/45 R 18 95 V
Tyre size RL				225/45 R 18 95 V
Tyre size RR				225/45 R 18 95 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259


Assistance equipment

Repair kit	Yes	Compressor	Yes
MOT certificate, Missing, Replace			





Bumper F, Scratch(es), Repair and paint (complete)



Headlight L, Scratch(es), Replace



Bumper moulding F, Scratch(es), Acceptable



Wing FL, Scratch(es), Spot repair



Alloy rim FL polished, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing L, Scratch(es), Acceptable



Door FL, Scratch(es), Acceptable



Door RL, Scratch(es), Acceptable



Alloy rim RL polished, Scratch(es), Repair and paint (complete)



Wing RL, Scratch(es), Acceptable



Tailgate / Boot, Scratch(es), Acceptable



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)



Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Kenteken	2AQM010
Merk Model	Mercedes CLA180 Sedan 1.3i 136pk/cv 4p
Brandstofsoort	Benzine
Datum deel1	6/11/21

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
6/25/25	63,515	klein materiaal	
6/25/25	63,515	mercedes assyst b	Uitvoeren
6/25/25	63,515	remblokken achter	Vervangen
6/25/25	63,515	remschijven en blokken vooraan	Vervangen
6/25/25	63,515	ruitenswisserrubber vooraan	Vervangen
5/30/24	50,810	batterij	Vervangen
5/30/24	50,810	dakgel. smeren	Uitvoeren
5/30/24	50,810	klein materiaal	Uitvoeren
5/30/24	50,810	mercedes assyst a	Uitvoeren
5/30/24	50,810	remvloeistof	Vervangen
5/30/24	50,810	ruitenswisserrubber vooraan	Vervangen
6/6/23	37,219	klein materiaal	
6/6/23	37,219	mercedes assyst b	Uitvoeren
6/6/23	37,219	trekhaak	Controleren
5/16/22	18,490	klein materiaal	
5/16/22	18,490	mercedes assyst a	Uitvoeren
5/16/22	18,490	ruitenswisserrubber vooraan	Vervangen