



Peugeot 3008: 1YXB949

Vinnnumber:	VF3MCYHZUMS012741	Versionname:	
First Registrationdate:	19/01/2021	Fiscalpower:	
Expertise Mileage:	65460	Power Kw:	
Bodytype:		Body colour	Black
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:	Front		
Fueltype:	Diesel		
Maintenance	OK		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options

Number of keys total	2	Central consol F	
Number keys remote	2	Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Board Computer			
Cruise Control			
Steering wheel multifunction			
Steering wheel leather			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Type of radio	Multimedia		
Type of GPS storage	HD		

Tyres

215/65/17/99 V				
Winter tyres:	Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 6 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				7.0
Tyre profile depth RR				7.0
Tyre size FL				215/65 R 17 99 V
Tyre size FR				215/65 R 17 99 V
Tyre size RL				215/65 R 17 99 V
Tyre size RR				215/65 R 17 99 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				259
Tyre make FR				259
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Bumper moulding F, Scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Acceptable



Bumper spoiler F, Chemical polution, Acceptable



Step L, Scratch(es), Acceptable



Alloy rim RL, Scratch(es), Acceptable



Wing trim RL, Scratch(es), Replace



Wing RL, Scratch(es), Acceptable



Boot carpet, Stain, Cleaning



Boot carpet, Damaged, Smart repair



Internal boot lining R, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Smart repair



Bumper trim R, Scratch(es), Smart repair



Tailgate / Boot, Scratch(es), Acceptable



Step R, Scratch(es), Acceptable



Door RR, Scratch(es), Acceptable



Wing FR, Scratch(es), Acceptable



Bodywork, Not original part, Sticker removal

