MACADAM










OPEL CORSA: GS-278-BZ

Vinnumber:	**VXKUPHNKSP4136022**	Versionname:	**OPEL CORSA 1.2 Turbo 100ch auto Elegance Business VP [5P] bva 8-101CH-5cv (bi-corps)**
First Registrationdate:	**27/10/2023**	Fiscalpower:	
Expertise Mileage:	**47979**	Power Kw:	**74**
Bodytype:	**Berline**	Body colour	**Grey**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Petrol**	Type of rims (mounted)	**Aluminium**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Category	**Passenger Car**		

Options

Number of keys total	**1**	Radio	
Number keys remote	**1**	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Seat cover lining	**Lining Other**
Steering wheel leather			
Type of climate control	**Manual climate control**		

Tyres

Summer tyres:	**195/55/16/91 H**			
	Fr.L.	**Goodyear: 50%**	Fr.R.	**Goodyear: 50%**
	Re.L.	**Goodyear: 30%**	Re.R.	**Goodyear: 30%**

Tyre profile depth FL	**5.0**
Tyre profile depth FR	**5.0**
Tyre profile depth RL	**6.1**
Tyre profile depth RR	**6.1**
Tyre size FL	**195/55 R 16 91 H**
Tyre size FR	**195/55 R 16 91 H**
Tyre size RL	**195/55 R 16 91 H**
Tyre size RR	**195/55 R 16 91 H**
Tyre type FL	**All seasons**
Tyre type FR	**All Seasons**
Tyre type RL	**All seasons**
Tyre type RR	**All Seasons**
Tyre make FL	**259**
Tyre make FR	**259**
Tyre make RL	**259**
Tyre make RR	**259**

Assistance equipment

Remote ignition key, Missing, Repair/replace (lump sum)



Alloy rim FL, Scratch(es), Repair/replace (lump sum)



Alloy rim FR, Scratch(es), Repair/replace (lump sum)



Door RL, Scratch(es), Paint



Door FL, Scratch(es), Paint



Wing FL, Scratch(es), Paint



Wing RL, Stone chip(s), Paint



Bumper F, Scratch(es), Paint



Bonnet, Stone chip(s), Paint



Wing FR, Chemical polution, Polish



Bumper R, Scratch(es), Paint







ALPHABET

Historique Maintenance

Immatriculation: **GS-278-BZ** Date de 1ère immatriculation: **27/10/2023**

Modèle: **Opel CORSA 1.2 Turbo 100ch auto Elegance Business VP [5P] bva 8-101CH-5cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
08/10/2026	49.949	FLEET SOLUTIONS FRANCE	REVISION
			BALAIS ESSUIE GLACE AV AR
			BALAIS ESSUIE GLACE AV AR
			FILTRE CLIM RPLT
07/08/2025	29.989	KRYSTAL S.A.S	BALAIS ESSUIE GLACE AV
			REVISION
			FILTRE CLIM RPLT
			BALAI ESSUIE GLACE AR
02/12/2024	8.319	AUTOPLAN SERVICES	REVISION ET CLIM