



2-DRE-516


2-DRE-516 · WF0PXXGCHPPL84299 · 30 June 2026 · Zaventem (BE)

Specifications

| | | | |
|----------------------|-------------------|-------------------|-----------------------------------|
| License Plate Number | 2-DRE-516 | Fuel Type | Hybrid Gasoline |
| Manufacturer | FORD | VIN | WF0PXXGCHPPL84299 |
| Model | Focus | Cylinder Capacity | 999 ^{cm³} |
| Model Versions | WF0PXXGCHPPL84299 | Transmission Type | Handmatig geschakelde transmissie |
| Body Type | 5 door hatchback | First Admission | 02-06-2023 |
| Color | Blue | Odometer | 72.242 ^{Km} |
| Paint Type | Metallic | Numer Of Keys | 2 |
| Production Year | 2023 | Interior | Black |
| KW | 92 | Number Headrests | 5 |

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Front & rear parking sensors

Leather steering wheel

Navigation system

Seat heating

Steering wheel multifunction

Steeringwheel - Heated

Windscreen - Heated

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs Unknown

Tire Specifications

| Tire | Profile | Brand | Width | Aspect Ratio | Radial | Type |
|-----------------|-----------------|----------|-------------------|------------------|--------------------|------------|
| Front Left | 3 ^{mm} | Goodyear | 215 ^{mm} | 50 ^{mm} | 17 ^{inch} | All Season |
| Rear Left | 5 ^{mm} | Goodyear | 215 ^{mm} | 50 ^{mm} | 17 ^{inch} | All Season |
| Front Right | 3 ^{mm} | Goodyear | 215 ^{mm} | 50 ^{mm} | 17 ^{inch} | All Season |
| Rear Right | 5 ^{mm} | Goodyear | 215 ^{mm} | 50 ^{mm} | 17 ^{inch} | All Season |
| Spare Tire Type | Compressor | | | | | |

Damages



Damage Part

Fender - Rear Left

Damage Type

small dents / small scratches

Repair Type

Panelbeating & Spray

Acceptable

No



Damage Part

Reardoor - Left

Damage Type

Scratch(es)

Repair Type

Polish

Acceptable

No



Damage Part

Frontdoor - Left

Damage Type

Door-edge chipped

Repair Type

Acceptable

Acceptable

Yes



Damage Part

Damage Type

Repair Type

Acceptable

Hood

Stonechipping

Acceptable

Yes



Damage Part

Damage Type

Repair Type

Acceptable

Bumper - Front

Scratch(es)

Spray

No



Damage Part

Damage Type

Repair Type

Acceptable

Frontdoor - Right

Door-edge chipped

Acceptable

Yes



Damage Part

Reardoor - Right

Damage Type

Scratch(es)

Repair Type

Polish

Acceptable

No



Damage Part

Fender - Rear Right

Damage Type

Small scratch(es)

Repair Type

Polish

Acceptable

No



Damage Part

Bumper - Rear

Damage Type

Scratch(es)

Repair Type

Spray

Acceptable

No



Damage Part

Damage Type

Repair Type

Acceptable

Tailgate

Small scratch(es)

Touch-up / Polish

No



Damage Part

Damage Type

Repair Type

Acceptable

Windscreen - Front

Chipped

Window Repair

No



Damage Part

Damage Type

Repair Type

Acceptable

Trunkshelf

Missing

Replace

No