



Volvo XC60: S158KS

Vinnumber:	YV1UZH1V2P1322802	Versionname:	XC60 T6 PHEV 257kW AWD Core-Bright automaat
First Registrationdate:	22/02/2023	Fiscalpower:	
Expertise Mileage:	107067	Power Kw:	186
Bodytype:		Body colour:	Denim Blue metallic
Gearbox:	Automatic	Paint type:	Metallic
Transmission:		Type of rims (mounted):	Aluminium
Fueltype:	Hybrid Petrol	Parking lot:	1137
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	No		

Options

Number of keys total	2	Lining leather
GPS		Sun Roof electric
Autom climate control		Panoramic roof
Radio multimedia		Rear parking sensors
		Hook

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	235 / 60 / 18 / 107 / H / Aluminium	5,1 mm	Michelin	Winter
	Right	235 / 60 / 18 / 107 / H / Aluminium	5,2 mm	Michelin	Winter
Rear	Left	235 / 60 / 18 / 107 / H / Aluminium	5,0 mm	Michelin	Winter
	Right	235 / 60 / 18 / 107 / H / Aluminium	5,0 mm	Michelin	Winter

Assistance equipment

Number of charging cables (rapid charge)	1
--	----------

Roof pillar L, Scratch(es), Repair and paint (complete)



Wing RL, Scratch(es), Repair and paint (complete)




Door RL, Scratch(es), Repair and paint (complete)



Windscreen, Stone chip(s), Windscreen repair



Bonnet, Chemical polution, Polish



Bumper F, Crack, Repair and paint (complete)



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Bumper RM, Scratch(es), Repair and paint (complete)



Kenteken	S158KS
Merk Model	Volvo XC60 T6 PHEV 257kW AWD Core-Bright automaat
Brandstofsoort	Benzine
Datum deel1	22-02-23

Datum reparatie	Kilometerstand	Reparatie omschrijving
21-10-25	92.150	Onderhoudsbeurt
21-10-25	92.150	Volvo Check slijtagedelen
18-12-24	64.669	Bougie
18-12-24	64.669	Luchtfilter
18-12-24	64.669	Onderhoudsbeurt
18-12-24	64.669	Ruitenwischerblad(en) voorzijde
18-12-24	64.669	Vervanging band
18-12-24	64.669	Volvo Check aandrijving
18-12-24	64.669	Volvo Check slijtagedelen
23-01-24	33.632	Onderhoudsbeurt
23-01-24	33.632	Volvo Check slijtagedelen