



Expertise

Protocol number: 46838592
Order No. / Reference: 26580685
Inspection date: 31 Jul 2026

Manufacturer: Opel

Model: Insignia Sports Tourer 2.0 Diesel 4x4 Aut. Business

VIN: W0VZT8EP4N1000948



Vehicle details	
Manufacturer / Type / Model / Equipment	
Opel Insignia Sports Tourer 2.0 Diesel 4x4 Aut. Business	
Vehicle Identification number	W0VZT8EP4N1000948
Mileage (Read)	114,667 km
First registration	31 Jan 2022
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,995 ccm / 4
Power	128 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	All-wheel drive
Type of vehicle	Station wagon
Colour / colour code	Diamant Schwarz Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black-Anthracite



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	7 Monat(e)
Last service on / at	02/2026 at 102,989 km		
Key is / should be	1 / 2	FZG documents	Registration and title documents unavailable
		Letter No.	GJ627529
Previous damage / Accident	Detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	1844 / AMJ 00073		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,330 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R17 97W	Summer tyres on Light alloy	Bridgestone	3mm / 3mm
2)	225/55 R17 97W	Summer tyres on Light alloy	Bridgestone	3mm / 3mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R17 105V	Winter tyres on Light alloy	Semperit	4mm / 4mm
2)	225/55 R17 105V	Winter tyres on Light alloy	Semperit	4mm / 4mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 12/2025		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Equipment

- Klimaautomatik

Standard equipment

- | | |
|--|---|
| <ul style="list-style-type: none"> • Storage compartments • Airbag: Front and rear outer head airbags • All-wheel drive 4x4 • Anti-lock braking system (ABS) • Hill Start Assist • third brake light • Decorative strip hexagon • Tachometer • Electronic Stability Program (ESP Plus) • Front collision warning system with pedestrian detection and automatic emergency braking • Speed controller • Back window, heater • Child safety lock in the rear doors, manual • Front headrests • LED headlights • LED daytime running lights including LED indicators, front and LED taillights • Center armrest, front • Electric parking brake • Upholstery: Monita fabric/Premium leather look including Winter Package 2 • Radio: Multimedia Navi Pro with 8" color touchscreen display • Wheels: 7.5 J x 17 alloy wheels in a 5 double-spoke design • Seat belts: Three-point seat belts in all seats • Visibility equipment • Start/Stop System • Traction Control (TC) Plus • Pre-installation for child seat mounting system "ISOFIX" • Thermal insulation glazing, green tinted • Second folding ignition key | <ul style="list-style-type: none"> • Airbag: Front airbags and side airbags, driver and front passenger • Ambient lighting • Electrically adjustable and heated exterior mirrors for driver and passenger side • Roof rails, silver anodized • Diesel particulate filter • Electronic brake force distribution (EBD) • Electric windows front and rear • Pedestrian protection including active hood • luggage compartment cover • Transmission: 8-speed automatic transmission • rear window wiper • Automatic climate control, two zones • Rear headrests (3 pieces) • LED fog lights • Steering column adjustable for height and reach • Illuminated makeup mirrors in both sun visors • Package: Winter 1 (AGR, Driver) • Parkpilot, front and rear parking aid • Quickheat rapid heating system • Radio: Digital radio reception DAB+ • Tire repair kit • Tire pressure gauge • Rear seat backrest folds forward in a 60:40 split • Power steering • safety net • Lane Keeping Assist • Bumpers painted in body color • Traffic sign assistant • Immobiliser • Central locking with remote control |
|--|---|

Extra equipment

- | | |
|--|---|
| <ul style="list-style-type: none"> • Paint finish: Metallic | <ul style="list-style-type: none"> • WKR |
|--|---|

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 1 (registration document) and the vehicle registration certificate Part 2 (title) were not available.
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.



Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Boot lid / rear door	Boot lid - dent(s) - Smooth repair work
3	Door - front right side	Door - Scratch(es) - Paint
4	Rear bumper	Rear bumper - Scratch(es) - Paint
5	Door - rear right side	Door - Dent / paintcoat damage - Repair and paint

Missing parts

Description

Equipment - Vehicle key

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Provided by user / customer, from 21 Jun 2025	2.497,61 €
2	Rear, Provided by user / customer, from 25 May 2025	4.099,77 €
3	Side - left, Provided by user / customer, from 20 Oct 2023	6.817,04 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.



Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Additional tyres



Figure 16: Additional tyres



Figure 17: Additional tyres



Figure 18: Additional tyres



Figure 19: Navigation



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.





Figure 32: Misc.



Damage 1: Equipment: Tirefit filler - Expired - Replace



Damage 2: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



Damage 2: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



Damage 4: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 4: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 5: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint



Damage 5: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint



Damage 5: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint



Missing part 1: Equipment: Vehicle key - Missing - Replace



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W0VZT8EP4N1000948

Hersteller / Modell: OPEL OPEL Insignia Sports Tourer 2.0 Diesel 4x4 Aut. Business

Datum	KM-Stand	Beschreibung
03.02.2026	102.989	Bremsflüssigkeit; Bremsflüssigkeit ern; Bremsklötze vorne; Bremsscheiben + Klötze v; Bremsscheiben vorne; Kraftstofffilter ern; Luftfiltereinsatz ern; Regelwartungsdienst
06.01.2026	99.611	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges
23.01.2025	70.324	HU + AU; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Systemtest/ Eigendiagnose; Wartung Sonstiges
16.01.2024	51.152	Bremse Sonstiges; Bremsflüssigkeit; Bremsflüssigkeit ern; Bremsscheiben + Klötze h; Bremsscheiben hinten; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
09.02.2023	27.876	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges