MACADAM







Opel Grandland (UKL): 2CJS559

Vinnumber:	**W0VZCYHZ9N6824668**	Versionname:	**Grandland Ultimate 1.5 Turbo D S/S 130pk/cv 5p Aut.**
First Registrationdate:	**16/08/2022**	Fiscalpower:	
Expertise Mileage:	**147584**	Power Kw:	**96**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Diesel**		
Maintenance	**OK**		
Maintenance	**+ 16800 km**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of Maintenance book	**Maintenance book present**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**225/55/18/98 V**			
	Fr.L.	**Bridgestone: 4 mm**	Fr.R.	**Bridgestone: 4 mm**
	Re.L.	**Bridgestone: 5 mm**	Re.R.	**Bridgestone: 4 mm**

Tyre profile depth FL	**4.0**
Tyre profile depth FR	**4.0**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**4.0**
Tyre size FL	**225/55 R 18 98 V**
Tyre size FR	**225/55 R 18 98 V**
Tyre size RL	**225/55 R 18 98 V**
Tyre size RR	**225/55 R 18 98 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**255**
Tyre make FR	**255**
Tyre make RL	**255**
Tyre make RR	**255**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**

Bumper F, Scratch(es), Spot repair








Bumper moulding F, Scratch(es), Repair and paint (complete)








Alloy rim FL polished, Scratch(es), Acceptable




Bumper R, Scratch(es), Acceptable





Wing trim FR, Scratch(es), Repair and paint (complete)




Door RR, Scratch(es), Acceptable




Onderhoudshistorie van: W0VZCYHZ9N6824668

ALPHABET

Kenteken	2CJS559
Merk Model	Opel Grandland Ultimate 1.5 Turbo D S/S 130pk/cv 5p Aut.
Brandstofsoort	Diesel
Datum deel1	8/16/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
7/8/25	101,967	102000 km	Uitvoeren
7/8/25	101,967	oliezeef	Vervangen
7/8/25	101,967	ruitenwisserrubber vooraan	Vervangen
11/27/24	81,469	80000 km	Uitvoeren
11/27/24	81,469	oliezeef	Vervangen
5/15/24	55,123	50000 km	Uitvoeren
5/15/24	55,123	brandstof hoofdfilter	Vervangen
5/15/24	55,123	luchtfilter	Vervangen
5/15/24	55,123	luchtfilter interieur	Vervangen
5/15/24	55,123	oliezeef	Vervangen
6/12/23	28,619	oliezeef	Vervangen
6/12/23	28,619	onderhoud 12 maand	Uitvoeren