



RENAULT Megane: 1238-MDY

Vinnumber:	VF1RFB00270664875	Versionname:	S.T. Techno Blue dCi 85 kW (115CV) EDC familiar 85kW 5P automática
First Registrationdate:	16/02/2023	Fiscalpower:	
Expertise Mileage:	137584	Power Kw:	
Bodytype:	Break	Body colour:	White
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:			
Fueltype:	Diesel		
Engine functioning:	Yes		
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total	2	Central consol F
Number keys remote	2	Luggage cover
GPS big screen color		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		Roof bar alu
Cruise Control		
Steering wheel multifunctional		
Steering wheel leather		
Radio multimedia		
Type of climate control	Autom climate control	

Tyres

205/50/17/93 V				
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				205/50 R 17 93 V
Tyre size FR				205/50 R 17 93 V
Tyre size RL				205/50 R 17 93 V
Tyre size RR				205/50 R 17 93 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Spare wheel	Yes	Jack	Yes
Interior, Dirty, Cleaning			



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Alloy rim RL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Door RL, Scratch(es), Acceptable



Outside rear-view mirror housing L, Scratch(es), Acceptable



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Wing FL, Scratch(es), Acceptable



Bumper F, Scratch(es), Repair and paint (complete)



Bonnet, Dent(s) and scratch(es), Repair and paint (complete)



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Outside rear-view mirror housing R, Scratch(es), Repair and paint (complete)



Wing FR, Dent(s) and scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Acceptable



Bumper R, Scratch(es), Repair and paint (complete)



Tailgate / Boot, Scratch(es), Acceptable



Tyres, No damage, Check

