MACADAM









CITROÃ‹N C3: FR-919-RR

Vinnumber:	**VF7SXYHYPLT576345**	Versionname:	**CITROÃ‹N C3 BlueHDi 100 S&S BVM Feel Business VP [5P] bvm 5-102CH-5cv (bi-corps)**
First Registrationdate:	**27/07/2020**	Fiscalpower:	
Expertise Mileage:	**97871**	Power Kw:	**75**
Bodytype:	**Berline**	Body colour	**Grey**
Gearbox:	**MAN 5 VIT**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Grey**
Fueltype:	**Diesel**	Type of rims (mounted)	**Steel**
Engine functioning	**Yes**	Dashboard color	**Grey**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Steel**		
Category	**Passenger Car**		

Options

Number of keys total	**1**	Radio	
Number keys remote	**1**	Luggage cover	
GPS big screen color		Rear parking sensors	
Windows electric F		Seat cover lining	**Lining Other**
Cruise Control			
Steering wheel multifunctional			
Type of climate control	**Autom climate control**		

Tyres

Summer tyres:	**185/65/15/88 H**			
	Fr.L.	**Hankook: 60%**	Fr.R.	**Hankook: 60%**
	Re.L.	**Hankook: 45%**	Re.R.	**Hankook: 45%**

Tyre profile depth FL	**4.3**
Tyre profile depth FR	**4.2**
Tyre profile depth RL	**5.4**
Tyre profile depth RR	**5.3**
Tyre size FL	**185/65 R 15 88 H**
Tyre size FR	**185/65 R 15 88 H**
Tyre size RL	**185/65 R 15 88 H**
Tyre size RR	**185/65 R 15 88 H**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**260**
Tyre make FR	**260**
Tyre make RL	**260**
Tyre make RR	**260**

Assistance equipment

Interior, Stain, Cleaning







Remote ignition key, Missing, Repair/replace (lump sum)



Wheel cover FR, Broken, Replace




Wheel cover FL, Broken, Replace




Outside rear-view mirror housing L, Scratch(es), Paint




Outer door handle FL, Scratch(es), Paint




Door FL, Scratch(es), Paint




Bumper F, Scratch(es), Paint





Side repeater R, Broken, Replace




Rubber seal for boot lid, Unclasped, Dismount/Mount




Luggage cover stopper, Missing, Replace





ALPHABET

Historique Maintenance

Immatriculation: **FR-919-RR** Date de 1ère immatriculation: **27/07/2020**

Modèle: **Citroen C3 BlueHDi 100 S&S BVM Feel Business VP [5P] bvm 5-102CH-5cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
14/04/2025	76.168	GARAGE DE LA GARE	REVISION
29/07/2024	60.170	GARAGE DE LA GARE	BATTERIE RPLT
	0		DIAG
15/07/2024	59.981	SOLLIES AUTO SECURITE	CONTROLE TECHNIQUE
20/03/2024	52.283	CARROSSERIE BEL'ANGE	FILTRE A AIR RPLT
	0		REVISION
	0		LIQUIDE DE FREIN
	0		REVISION
	0		RECYCLAGE
	0		FILTRE CLIM RPLT
	0		DISQUES PLAQUETTES AV RPLT
26/06/2023	35.040	CARROSSERIE BEL'ANGE	RESERVOIR ADBLUE RPLT
31/01/2023	30.400	CHOPARD CANNES MOUGINS	FILTRE CLIM RPLT
	0		REVISION
	0		RECYCLAGE
	0		BALAIS ESSUIE GLACE AV
06/10/2021	8.005	GARAGE ANTONELLI ET FILS	REVISION