



CITROËN BERLINGO: EX-781-VN

Vinnumber:	VF77BBHY6JJ691702	Versionname:	CITROËN BERLINGO BlueHDi 100 BVM Club M VU [3P] bvm 5-100CH-5cv (fourgonnette-)
First Registrationdate:	31/05/2018	Fiscalpower:	
Expertise Mileage:	155482	Power Kw:	73
Bodytype:	Transporter	Body colour:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Steel
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	4		
Number of seats:	3		
Number head rests:	3		
Type of rims (mounted):	Steel		
Category:	Light Commercial Vehicle		

Options

Number of keys total:	2	Radio:	
Number keys remote:	1	Rear parking sensors:	
Windows electric F:		Seat cover lining:	Lining Other
Cruise Control:			
Type of climate control:	Manual climate control		

Tyres

	195/65/15/91 H			
Summer tyres:	Fr.L.	Bridgestone: 75%	Fr.R.	Bridgestone: 80%
	Re.L.	Bridgestone: 70%	Re.R.	Bridgestone: 55%
Tyre profile depth FL				3.2
Tyre profile depth FR				3.1
Tyre profile depth RL				3.8
Tyre profile depth RR				4.6
Tyre size FL				195/65 R 15 91 H
Tyre size FR				195/65 R 15 91 H
Tyre size RL				195/65 R 15 91 H
Tyre size RR				195/65 R 15 91 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				255
Tyre make FR				255
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Spare wheel:	Yes	Jack:	Yes
Interior, Dirty, Cleaning			





Tyre FR, Out of tolerance, Replace



Tyre FL, Out of tolerance, Replace



Tyre RL, Out of tolerance, Replace



Wing FL, Scratch(es), Acceptable



Side panel L, Scratch(es), Paint



Outer sill L, Dent(s) and scratch(es), Repair and paint (complete)



Side panel moulding L, Scratch(es), Replace



Bonnet, Stone chip(s), Paint





Grille, Unclassped, Dismount/Mount



Outside rear-view mirror housing R, Scratch(es), Replace



Boot door panel RL, Dent(s) and scratch(es), Repair and paint (complete)

