BMW

BMW 2 GRAN COUPE (F44)(2019->) 218I ADVANTAGE MOTEUR 1,5 LITRE(S) - 100 KW 12V 4 PORTES

VIN: WBA11AK0907L21723



Description

Registration number 2CCR625	**Registration date** 07/06/2022	**Odometer** 101894 km
Color SKYSCRAPER GRAU METALLIC	**Year** 2020	**Upholstery** -
Number of doors 4	**Number of seats** 5	**Generation** -
CO2 148	**Engine displacement** 1499	**Gearbox type** Automatic
Engine type Combustion	**Fuel Type** Petrol	**Number of gears** 7
Drivetrain Front Wheel Drive (FWD)	**Max power** 100 KW	

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Vehicle Equipments

Standard

armrest front	Advantage	airbag driver side/passenger side
airbag passenger side deactivatable	sidebag front	generator 120 A
Batterie Vlies-tec (électrolythe gel) 60 Ah (AGM)	BMW Live cockpit Professional	start-stop button
active hood	body: 4-door	automatic air-conditioning system
tire pressure control system	radio reception digital (DAB)	power steering Servotronic
theft protection for wheels (rim locks)	dynamic stability control (DSC) with extended scope	light and rain sensor
anti-theft warning system + interior scanning / towing protection + back-up alert horn	Entretien: Véhicule avec Intervalle de vidange d'huile 30000 Km / 24 mois	interior equipment interior trim strips Quartz silver matte Grained
gasoline particulate filter (GPF)	refrigerant R 1234 YF	parking brake electromechanical
windshield washer jets heated	Light-alloy rims	vehicle speed limiter
window lifter electric front + rear	model variant CO2 scope (code 1CB)	engine 1,5 liter - 100 kW 12V catalyst
low emissions according to emission standard Euro 6d	trip computer	Equipment package: Connected Professional
Service system: Apple CarPlay information (preparation)	Service system: Remote Services	infotainment system: Cadillac User Experience (CUE) with touchscreen
Service system: Real Time Traffic Information (RTTI)	Service system: On-Street Parking	Storage package
Parkpilot system front and rear	headlight LED (extended scope)	cruise control with brake function
exterior mirror electrically adjustable and heated	seat covers/upholstery: cloth Grid	Isofix mounts for child seat at rear seat
Isofix mounts for child seat at passenger seat	Suppression Touch fonction BMW Controller	floor mats velours
head airbag system rear	head airbag system front	antilock braking system (ABS)
driver assistance system: Active Guard plus (lane assist, front-end collission warning)	driver assistance system: Performance Control	driver assistance system: alertness assistant
personalization system (Personal Profile)	Service system: intelligent emergency call incl. TeleServices	Service system: ConnectedDrive Services
Service system: legally required emergency call feature	start/stop system	warning triangle
Steering AV European market (EU specific)	central locking system	steering wheel (sport/leather) with multiple function

Optional

anti-theft warning system with intrusion protection	transmission 7-speed - dual-clutch transmission with Steptronic	tire repair kit
norme de dépollution Euro 6 RDE 2	metallic paintwork	interior mirror with automatic dimming
seat front right mechanical height-adjustable		

Statement details

Inspection loc	Statement date	Inspection approval date
PARC HÖDLMAYR TONGEREN	13/10/2026	15/10/2026


Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Defects & corrections

#	Element	Defect	Correction
001	Door / Back Right	Dent	Acceptable
			
002	Door / Front Right	Dent	Acceptable
			
003	Wing / Back Left [1]	Improper Repair	Painting
	   		
004	Bumper / Back Painted : Yes	Improper Repair	Painting
	   		
005	Bumper / Front Painted : Yes	Improper Repair	Painting
	  		

[1] Kleurverschil

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Loose Items

- [x] Document holder
- [x] Registration certificate owner
- [x] Registration certificate
- [x] Triangle
- [x] Rear parcel shelf
- [x] Spare Key
- [x] First aid kit
- [x] Conformity certificate
- [x] Safety vest

Main set of tyres

Front Left	MICHELIN	205/55/16 Winter	5 mm
Front Right	MICHELIN	205/55/16 Winter	5 mm
Back Left	MICHELIN	205/55/16 Winter	7 mm
Back Right	MICHELIN	205/55/16 Winter	7 mm

Comments

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures



Front left



Rear left



Boot opened



Rear right



Rear passenger compartment



Dashboard from rear seat



Front passenger compartment



Front right



Odometer



Navigation




Spare Tyre




Vin


All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Other



Other



Other



Other



Door / Back Right / Dent



Door / Front Right / Dent



Wing / Back Left / Improper Repair



Wing / Back Left / Improper Repair



Wing / Back Left / Improper Repair



Wing / Back Left / Improper Repair



Bumper / Back / Improper Repair



Bumper / Back / Improper Repair



Bumper / Back / Improper Repair




Bumper / Back / Improper Repair



Bumper / Front / Improper Repair

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Bumper / Front / Improper Repair



Bumper / Front / Improper Repair

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.