APPRAISAL REPORT



VEHICLE IDENTIFICATION

Driver name:	HM Tongeren
Make:	VOLKSWAGEN
Model / version:	T-ROC CABRIOLET
Wine:	WVGZZZA1ZNK004345
Plate:	2BJU138
Mileage:	134777
First registration:	13/12/2021
Color:	Smokey grey

ADDITIONAL INFORMATION

Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?


DOCUMENTS

Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	?
Maintenance book	
Number of keys:	2
Original key:	✓

PICTURES
























































WINE INFORMATION

Radio	6 speakers	Bluetooth
Manual transmission	6 reports	Convertible / Roadster
Automatic headlights	Material: alloy	Reference letter (J)
Front diameter 17	Rear diameter 17	Front width 7.0
Rear width 7.0	Front diameter 17	Rear diameter 17
Front height 55	Rear height 55	Forward speed index V
Rear speed index V	Front width 215	Rear width 215
Flat steel spare wheel	Automatic climate control	Air conditioning refrigerant 1234YF
Front center armrest	Chrome interior finish	Essence
1498 cm3	1.50 liters	110 kW
150 hp	140 Amp Alternator	Metallic varnished
Front disc brakes	Rear disc brakes	Heated left-side mirror

Heated right-side mirror
Electrically folding mirrors
Height-adjustable front left seat
Height-adjustable front seats
Fabric trim
Leather steering wheel
Multifunction steering wheel
Front parking assistance
Aide au stationnement arrière
Assistance au parking
Caméra avant
Caméra arrière de recul
Régulateur automatique de la distance
Equipement Stop & Start
Affichage lecture des panneaux de signalisation
Verrouillage centralisé à commande à distance
Carte mains libres
Appel de secours
détecteur de pluie essuie-vitre
Attelage avec boule amovible
Protection piéton
Assistant maintien de la voie
Freinage d'urgence assistée autonome (urbain)
Avertisseur de collision avant
depuis 09.21
pack brillance chromé
radio avec récepteur digital
pare-vent
éclairage d'ambiance de Type 1
suspension ar à 4 bras
indicateur d'usure des freins
entretien à intervalle flexible (Long Life)
Life
QI6
réservoir à charbon actif (EVAP)

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	✓	**Cruise control:**	?
Gps:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	✓
Front seats heated:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlighting type:		**Tow bar type:**	
Charging cables:	0	**Fast charging cables:**	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm		215/55R17 94V	Winter		?
Front right	5 mm		215/55R17 94V	Winter		?
Rear left	5 mm		215/55R17 94V	Winter		?
Rear right	5 mm		215/55R17 94V	Winter		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
2	Roof - Cabriodak reinigen	
3	Roof - 2X	Dent(s)
4	Alloy rim FL polished	Grooved
5	Inner door sill FL	Dent(s) and scratch(es)
6	Interior	Dirty
7	Alloy rim RL polished	Grooved
8	Alloy rim RR polished	Grooved
9	Alloy rim FR polished	Grooved

Total: 8

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
1	Cover insulation - Marterschade	Damaged	✓	✗	✗
1	Bodywork	Dent(s) and scratch(es)	✓	✗	✗

Total: 2

DAMAGES DETAILS

2 - Roof - Cabriodak reinigen







3 - Roof - 2X - Dent(s)






4 - Alloy rim FL polished - Grooved



5 - Inner door sill FL - Dent(s) and scratch(es)





6 - Interior - Dirty






7 - Alloy rim RL polished - Grooved






8 - Alloy rim RR polished - Grooved






9 - Alloy rim FR polished - Grooved







1 - Cover insulation - Marterschade - Damaged - Renta®





1 - Bodywork - Dent(s) and scratch(es) - Renta®











SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

16/09/2026 11:00

