

# Damage Review

|           |
|-----------|
| Jobnr     |
| Fleet     |
| Lease     |
| Driver    |
|           |
|           |
| Location  |
| Date      |
| Date Hour |

|                    |                   |
|--------------------|-------------------|
| Make               | DACIA             |
| Model              | NEW SANDERO       |
| Type               |                   |
| Licenseplate       | 2HAA358           |
| Chassisnr          | UU1DJF00674846510 |
| Color              | Bruin             |
| First Registration | 08-05-2025        |
| Mileage            | 24965             |
| VP/VU              | VP                |
| Fuel               | petrol            |
| Fuel Level         | 8/8               |
| Total Keys         | 1                 |
| Seats MVP          | 5                 |

|                   |     |                |     |
|-------------------|-----|----------------|-----|
| Check             |     |                |     |
| COC               | No  | Safety Kit     | Yes |
| Registration doc  | No  | Triangle       | Yes |
| Insurance doc     | No  | GPS            | Yes |
| Manual            | Yes | Fuel Card      | No  |
| Service book      | No  | Alarm          | Yes |
| Fire extinguisher | Yes | Service Needed | No  |
| Rear Shelf        | Yes |                |     |

## Remarks

## Signatures

This damage review contains the exterior and interior damages of the vehicle. The repair costs of the exterior and interior damage of the vehicle will be added afterwards. These repair costs will be part of the damage review. This norm is developed by Renta, the Belgian federation of rental companies.

This norm can be consulted on their website [www.renta.be](http://www.renta.be) . The Rentanorm is generally accepted by fleetowners and drivers as a guidance but is not binding in any way. This damage review does not count as an insurance/damage calculation as meant in the application of the law involved.

This signature means that I agree with the registered damages on my company car. I will receive a report of the registered damages by mail. This report contains no calculated damage amounts. Later the damage amounts will be calculated and added to this report, and then sent to the fleetmanager. Signing this report does not implicate my automatic acceptance of the damage amounts. A compensation on the damage amounts will be charged in accordance with the car policy of your company.



|          |                |                        |    |                    |                  |
|----------|----------------|------------------------|----|--------------------|------------------|
| exterior | 16 Roof        | ROOF-PILLAR R          | NA | scratch            | SR - Polish      |
| exterior | 13 BumperR     | BUMPER REAR            | NA | scratch            | Paint            |
| exterior | 15 BonnetR     | BONNET                 | NA | dent               | SR - PDR         |
| exterior | 15 BonnetR     | WIPER                  | NA | missing            | Replace          |
| exterior | 13 BumperR     | BUMPERPART NOT PAINTED | NA | scratch            | SR - Structure   |
| exterior | 16 Roof        | ROOF                   | NA | scratch            | Paint            |
| exterior | 1 BumperF      | MOLDING RIGHT          | NA | scratch + dent     | Replace          |
| exterior | 22 MirrorR     | CAP PAINTED            | NA | scratch            | Paint            |
| exterior | 30 Extra       | STICKERS               | NA | Remainder stickers | Remove stickers  |
| exterior | 29 Cleaning    | CLEANING               | NA | stain              | Cleaning         |
| exterior | 13 BumperR     | SPOILER REAR           | A  | scratch            | SR - Structure   |
| exterior | 23 WingFR      | COVER WING FR          | A  | scratch            | SR - Structure   |
| interior | 18 CarpetTrunk | REAR COVER             | A  | scratch            | Paint            |
| exterior | 20 SillR       | SILLR                  | A  | scratch            | SR - Spot repair |

## General Pictures





Damage Appraisal



|          |         |               |            |             |
|----------|---------|---------------|------------|-------------|
| exterior | 16 Roof | ROOF-PILLAR R | NA scratch | SR - Polish |
|----------|---------|---------------|------------|-------------|




|          |            |             |            |       |
|----------|------------|-------------|------------|-------|
| exterior | 13 BumperR | BUMPER REAR | NA scratch | Paint |
|----------|------------|-------------|------------|-------|



|          |            |        |         |          |
|----------|------------|--------|---------|----------|
| exterior | 15 BonnetR | BONNET | NA dent | SR - PDR |
|----------|------------|--------|---------|----------|



|          |            |       |            |         |
|----------|------------|-------|------------|---------|
| exterior | 15 BonnetR | WIPER | NA missing | Replace |
|----------|------------|-------|------------|---------|



|          |            |                           |            |                |
|----------|------------|---------------------------|------------|----------------|
| exterior | 13 BumperR | BUMPERPART NOT<br>PAINTED | NA scratch | SR - Structure |
|----------|------------|---------------------------|------------|----------------|



|          |         |      |            |       |
|----------|---------|------|------------|-------|
| exterior | 16 Roof | ROOF | NA scratch | Paint |
|----------|---------|------|------------|-------|



|          |           |               |                   |         |
|----------|-----------|---------------|-------------------|---------|
| exterior | 1 BumperF | MOLDING RIGHT | NA scratch + dent | Replace |
|----------|-----------|---------------|-------------------|---------|



|          |            |             |            |       |
|----------|------------|-------------|------------|-------|
| exterior | 22 MirrorR | CAP PAINTED | NA scratch | Paint |
|----------|------------|-------------|------------|-------|



|          |          |          |                       |                 |
|----------|----------|----------|-----------------------|-----------------|
| exterior | 30 Extra | STICKERS | NA Remainder stickers | Remove stickers |
|----------|----------|----------|-----------------------|-----------------|



|          |             |          |          |          |
|----------|-------------|----------|----------|----------|
| exterior | 29 Cleaning | CLEANING | NA stain | Cleaning |
|----------|-------------|----------|----------|----------|



|          |            |              |           |                |
|----------|------------|--------------|-----------|----------------|
| exterior | 13 BumperR | SPOILER REAR | A scratch | SR - Structure |
|----------|------------|--------------|-----------|----------------|



|          |           |               |           |                |
|----------|-----------|---------------|-----------|----------------|
| exterior | 23 WingFR | COVER WING FR | A scratch | SR - Structure |
|----------|-----------|---------------|-----------|----------------|



|          |                |            |           |       |
|----------|----------------|------------|-----------|-------|
| interior | 18 CarpetTrunk | REAR COVER | A scratch | Paint |
|----------|----------------|------------|-----------|-------|



|          |          |       |           |                  |
|----------|----------|-------|-----------|------------------|
| exterior | 20 SillR | SILLR | A scratch | SR - Spot repair |
|----------|----------|-------|-----------|------------------|



|                          |                                        |
|--------------------------|----------------------------------------|
| <b>Vehicle Condition</b> | Interior: clean<br><br>Exterior: clean |
|--------------------------|----------------------------------------|

|                    |        |                    |    |
|--------------------|--------|--------------------|----|
| <b>Tyres</b>       |        |                    |    |
| <b>Type</b>        | Summer | <b>Flat/RSC</b>    | No |
| <b>Spare Tyre</b>  | Yes    | <b>Repair Kit</b>  | No |
| <b>Front Left</b>  |        |                    |    |
| <b>Profile</b>     | 3      | <b>Side Damage</b> | No |
| <b>Front Right</b> |        |                    |    |
| <b>Profile</b>     | 3      | <b>Side Damage</b> | No |
| <b>Rear Left</b>   |        |                    |    |
| <b>Profile</b>     | 4      | <b>Side Damage</b> | No |
| <b>Rear Right</b>  |        |                    |    |
| <b>Profile</b>     | 4      | <b>Side Damage</b> | No |