



TOYOTA COROLLA: FS-917-YA

Vinnumber:	SB1K53BE00E049193	Versionname:	TOYOTA COROLLA Hybride 180h Dynamic Business VP [5P] bva 0-180CH-7cv (bi-corps)
First Registrationdate:	24/09/2020	Fiscalpower:	
Expertise Mileage:	999999	Power Kw:	132
Bodytype:	Berline	Body colour:	White
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Front	Interior colour:	Black
Fueltype:	Hybrid	Type of rims (mounted):	Aluminium
Engine functioning:	No	Dashboard color:	Black
Battery functioning:	No		
Vehicle running:	No		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Seats electric F L	
GPS big screen color		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Rear view camera	
Steering wheel leather		Seat cover lining	Lining Other
Type of climate control	Autom climate control		

Tyres

205/55/16/94 V				
Summer tyres:	Fr.L.	Michelin: 45%	Fr.R.	Michelin: 45%
	Re.L.	Michelin: 60%	Re.R.	Michelin: 50%
Tyre profile depth FL				5.3
Tyre profile depth FR				5.2
Tyre profile depth RL				4.3
Tyre profile depth RR				4.8
Tyre size FL				205/55 R 16 94 V
Tyre size FR				205/55 R 16 94 V
Tyre size RL				205/55 R 16 94 V
Tyre size RR				205/55 R 16 94 V
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Remote ignition key (no insert), Missing, Repair/replace (lump sum)



Seat cover FL, Stain, Cleaning



Steering wheel, Scratch(es), Replace



Alloy rim FL, Scratch(es), Repair/replace (lump sum)



Tyre RL, Tear, Replace



Alloy rim RL, Scratch(es), Repair/replace (lump sum)



Alloy rim RR, Scratch(es), Repair/replace (lump sum)



Alloy rim FR, Scratch(es), Replace



Wing FL, Dent(s), Repair and paint (complete)



Side repeater L, Scratch(es), Replace



Outside rear-view mirror housing L, Bad repair, Paint



Door FL, Scratch(es), Paint



Wing RL, Dent(s), Repair and paint (complete)



Bumper FR, Deformed / Strained, Repair and paint (complete)



Bumper spoiler F, Deformed / Strained, Replace and paint



Bumper FL, Deformed / Strained, Replace and paint



Side repeater R, Scratch(es), Replace



Bumper R, Scratch(es), Paint



Rear light L, Scratch(es), Replace



Roof, Dent(s), Repair and paint (complete)



Bodywork, Not original part, Remove lettering



Historique Maintenance

Immatriculation: **FS-917-YA** Date de 1ère immatriculation: **24/09/2020**
Modèle: **Toyota COROLLA Hybride 180h Dynamic Business VP [5P] bva 0-180CH-7cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
21/05/2025	100.619	ADL - AUTO DISTRIBUTION LANGUEDOCIENNE	BOITIER D ALLUMAGE RPLT
	0		LIQUIDE DE FREIN
	0		PLAQUE IMMATRICULATION AV RPLT
	0		REVISION ET CLIM
25/09/2024	81.730	ADL - AUTO DISTRIBUTION LANGUEDOCIENNE	LIQUIDE DE FREIN
	0		REVISION ET CLIM
	0		FILTRE A AIR RPLT
	0		BALAIS ESSUIE GLACE AV AR
16/09/2024	81.186	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
09/06/2023	47.557	ADL - AUTO DISTRIBUTION LANGUEDOCIENNE	REVISION ET CLIM
	0		LIQUIDE DE FREIN