



FORD TRANSIT: 1YLM343

Vinnumber:	WF0SXXWPGSLL47447	Versionname:	
First Registrationdate:	30/09/2020	Fiscalpower:	
Expertise Mileage:	208443	Power Kw:	74
Bodytype:		Body colour:	White
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Steel
Transmission:	Front		
Fueltype:	Diesel		
Maintenance:	OK		
Maintenance:	+ 30%		
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Type of rims (mounted):	Steel		
Certificate of Conformity:	Yes		
Category:	Light Commercial Vehicle		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Rear parking sensors:	2
Number keys remote:	1	Sliding door right-side:	1
Windows electric F:			
Board Computer:			
Steering wheel multifunctional:			
Type of headlighting:	Headlighting Halogen		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining fabrics		
Type of climate control:	Manual climate control		
Type of radio:	Multimedia		
Type of GPS storage:	HD		


Tyres

205/60/16/96 H				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				205/60 R 16 96 H
Tyre size FR				205/60 R 16 96 H
Tyre size RL				205/60 R 16 96 H
Tyre size RR				205/60 R 16 96 H
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Number of charging cables (normal):	0
Number of charging cables (rapid charge):	0

Dashboard, Hole, Smart repair



Dashboard, Scratch(es), Acceptable



Steering wheel, Worn, Acceptable



Seat cover FL, Incomplete, Repair/replace (lump sum)




Windscreen, Stone chip(s), Windscreen repair



Bumper F, Stone chip(s), Acceptable



Wheel cover RL, Broken, Replace



Wing RL, Dent(s), Paintless dent repair



Wheel cover FL, Scratch(es), Acceptable



Internal boot lining L, Broken, Replace



Wheel aperture RL, Dent(s) and scratch(es), Spot repair



Wheel aperture RR, Dent(s) and scratch(es), Spot repair



Boot carpet, Tear, Replace



Bumper R, Dent(s), Replace



Boot door panel RL, Dent(s) and scratch(es), Acceptable



Bumper moulding R, Dent(s) and scratch(es), Repair and paint (complete)





Internal boot lining R, Broken, Replace



Wheel cover FR, Scratch(es), Replace



Door FR, Dent(s) and scratch(es), Acceptable



Door RR, Dent(s) and scratch(es), Acceptable



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Wheel cover RR, Scratch(es), Acceptable



Door trim RR, Scratch(es), Smart repair



Bodywork, Not original part, Sticker removal

