MACADAM







Volkswagen ID.5 (KKL): 2FHZ970

Vinnumber:	**WVGZZZE26RP506802**	Versionname:	**ID.5 Pro Business Premium 77kWh 286pk/cv 5p**
First Registrationdate:	**17/05/2024**	Fiscalpower:	
Expertise Mileage:	**94381**	Power Kw:	**69**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Electric**		
Maintenance	**OK**		
Maintenance	**plus 569 d**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**Tow bar collapsible**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**235/55/19/105 W**			
	Fr.L.	**Vredestein: 4 mm**	Fr.R.	**Vredestein: 4 mm**
	Re.L.	**Vredestein: 4 mm**	Re.R.	**Vredestein: 4 mm**

Tyre profile depth FL	**4.0**
Tyre profile depth FR	**4.0**
Tyre profile depth RL	**4.0**
Tyre profile depth RR	**4.0**
Tyre size FL	**235/55 R 19 105 W**
Tyre size FR	**235/55 R 19 105 W**
Tyre size RL	**255/50 R 19 107 Y**
Tyre size RR	**255/50 R 19 107 Y**
Tyre type FL	**All seasons**
Tyre type FR	**All Seasons**
Tyre type RL	**All seasons**
Tyre type RR	**All Seasons**
Tyre make FL	**2480**
Tyre make FR	**2480**
Tyre make RL	**2480**
Tyre make RR	**2480**

Assistance equipment

Number of charging cables (normal)	**1**
Number of charging cables (rapid charge)	**1**

Interior, Stain, Cleaning







Bumper F, Scratch(es), Spot repair



Bumper grille, Scratch(es), Smart repair



Bonnet, Chemical polution, Polish




Door trim FL, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Acceptable



Rear spoiler, Chemical polution, Polish



Door RR, Scratch(es), Acceptable



Door FR, Dent(s), Paintless dent repair



Roof, Dent(s), Acceptable




Onderhoudshistorie van: WVGZZZE26RP506802

Kenteken	2FHZ970
Merk Model	Volkswagen ID.5 Pro Business Premium 77kWh 286pk/cv 5p
Brandstofsoort	Elektrisch
Datum deel1	5/17/24

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
5/5/26	73,537	klein materiaal	
5/5/26	73,537	luchtfilter interieur	Vervangen
5/5/26	73,537	Onderhoudsbeurt (variabel interval)	Uitvoeren
5/5/26	73,537	remvloeistof	Vervangen
5/5/26	73,537	ruitenwisserrubber vooraan	Vervangen
5/5/26	73,537	ruitenwisservloeistof	Bijvullen/-laden