



SKODA OCTAVIA COMBI: GT-105-TZ

Vinnumber:	TMBJR8NX6RY115733	Versionname:	SKODA OCTAVIA COMBI 1.5 TSI mHEV e-TEC 150 DSG7 Business VP [5P] bva 7-150CH-8cv (break)
First Registrationdate:	25/01/2024	Fiscalpower:	
Expertise Mileage:	166389	Power Kw:	110
Bodytype:	Break	Body colour:	White
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Front	Interior colour:	Black
Fueltype:	Hybrid	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	3	Radio	
Number keys remote	3	Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Headlights Xenon/LED/Laser	
Steering wheel leather		Rear parking sensors	
Type of climate control	Autom climate control	Rear view camera	
		Seat cover lining	Lining Other

Tyres

	205/60/16/96 V			
Summer tyres:	Fr.L.	Hankook: 25%	Fr.R.	Hankook: 30%
	Re.L.	Hankook: 70%	Re.R.	Hankook: 75%
Tyre profile depth FL				6.6
Tyre profile depth FR				6.1
Tyre profile depth RL				3.7
Tyre profile depth RR				3.4
Tyre size FL				205/60 R 16 96 V
Tyre size FR				205/60 R 16 96 V
Tyre size RL				205/60 R 16 96 V
Tyre size RR				205/60 R 16 96 V
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				260
Tyre make FR				260
Tyre make RL				260
Tyre make RR				260

Assistance equipment

Seat cover FR, Stain, Cleaning



Seat cover FL, Stain, Cleaning



Inner door sill FL, Dent(s) and scratch(es), Repair and paint (complete)



Tyre RR, Out of tolerance, Replace



Alloy rim RR, Scratch(es), Repair/replace (lump sum)



Tyre RL, Out of tolerance, Replace



Alloy rim FL, Scratch(es), Acceptable



Bumper F, Scratch(es), Paint



Boot lid covering R, Scratch(es), Replace





Internal boot lining R, Scratch(es), Replace



Internal boot lining R, Scratch(es), Replace



Bumper R, Scratch(es), Paint



Historique Maintenance

Immatriculation: GT-105-TZ Date de 1ère immatriculation: 25/01/2024

Modèle: Skoda OCTAVIA COMBI 1.5 TSI mHEV e-TEC 150 DSG7 Business VP [5P] bva 7-150CH-8cv (break)

Date	Kilométrage	Fournisseur	Descriptif
25/02/2026	150.122	LECLUSE AUTO LAVAL	LIQUIDE LAVE GLACE
	0		BALAI ESSUIE GLACE AR
	0		BALAIS ESSUIE GLACE AV
	0		DISQUES PLAQUETTES AR RPLT
	0		REVISION
25/02/2026	150.122	LECLUSE AUTOMOBILES LAVAL	DISQUES PLAQUETTES AR RPLT
	0		REVISION
	0		LIQUIDE LAVE GLACE
	0		BALAI ESSUIE GLACE AR
	0		BALAIS ESSUIE GLACE AV
16/10/2025	124.357	LECLUSE AUTOMOBILES LAVAL	AMORTISSEURS AV RPLT
	0		AMORTISSEURS AV CTRL
03/10/2025	121.445	LECLUSE AUTOMOBILES LAVAL	DISQUES PLAQUETTES AV RPLT
	0		REVISION ET CLIM ET AIR ET BOUGIES
	0		LIQUIDE LAVE GLACE
	0		PILE DE CLE RPLT
	0		LIQUIDE DE FREIN
12/05/2025	89.409	LECLUSE AUTOMOBILES LAVAL	LIQUIDE LAVE GLACE
	0		PLAQUETTES AR RPLT
	0		REVISION ET CLIM
	0		PILE DE CLE RPLT
27/12/2024	58.853	LECLUSE AUTOMOBILES LAVAL	BALAIS ESSUIE GLACE AV
	0		REVISION ET CLIM ET AIR ET BOUGIES
	0		LIQUIDE LAVE GLACE
	0		PILE DE CLE RPLT
	0		PLAQUETTES AV RPLT
	0		BALAI ESSUIE GLACE AR
24/07/2024	27.238	LECLUSE AUTOMOBILES LAVAL	LIQUIDE LAVE GLACE
	0		REVISION