MACADAM ITALY S.R.L.

Piazza Belgioioso, 2 - 20121 Milano (MI)

Tel. - Fax

Piva: 12729790969

| Report No. | Expert's report for | Type of insurance |
|---|---|---|
| | Alphabet Italia | Perizia |

| Policyholder | Opposite party | Opposite party company |
|---|---|---|
| | | |

| Operation | Claim number | Code / Agency | Date accident |
|---|---|---|---|
| 2026 | | | 06/10/2026 |

| Expert code | Adjuster code | Policy number | Injured person can recover the VAT |
|---|---|---|---|
| | | | |

| Date assignment | Date first survey | Place | C/O | Repairs | Photo | Lien in favor of | Expiry date |
|---|---|---|---|---|---|---|---|
| 06/10/2026 | 13/10/2026 | ROMA | VAR | TO START | | | |

Ownership certificate: Alphabet Italia - Via Romano Guardini 24 38121 Trento (TN) — Formerly plate:

Lessee / Co-owner — Date of overhaul:


| Vehicle (Brand - Model - Version) | Plate | Vin Chassis | First Registration |
|---|---|---|---|
| FIAT FIORINO 1.3 Multijet 95 CV E6d-final SX | GJ557YJ | ZFA22500006W33209 | 29/03/2022 |

| Usage status | Km | Tyres % | Color | Type of enamel | Consistency of damage | Type of Expert's report |
|---|---|---|---|---|---|---|
| NON CONOSCIUTO | 97845 | 50 | Bianco | PASTEL/DOUBLE | | NOT DEFINITIVE |

Equipment

| Approval code | For commercial vehicles | Carrying Qls | Tare,Q | Wheelbase | Seats No. | Axles |
|---|---|---|---|---|---|---|
| | | 0 | 0 | | 0 | 0 |

| Commercial value (C) | Wrecked car value | Value by difference | Ancillary expenses |
|---|---|---|---|
| | | | |




| | | Damaged items / restoration operations | | SR Dif | SR Time | LA Dif | LA Time | VE Dif | VE Time | ME Time | D.M. S.C. | Costs of spare parts * (VAT excluded) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 51812813 | Rear wheel cap | R | S | | S | | S | | | | |
| 1 | 735462098 | External rear-view mirror cap | R | S | | S | | S | | | | |
| 1 | 51812813 | Front wheel cap | R | S | | S | | S | | | | |
| 1 | 735666169 | Rear bumper | | S | | S | | S | | | | |
| 1 | 71792267 | Compressore a/c - ricondizionato | | S | | S | | S | | | | |
| 1 | 10852283 | Guarnizione tenuta | | S | | S | | S | | | | |
| 1 | 10852383 | Guarnizione tenuta | | S | | S | | S | | | | |
| 1 | 10877887 | Guarnizione tenuta | | S | | S | | S | | | | |
| 1 | Codice Ricambio | Ricarica a/c (gasr134a) con tracciante | | S | | S | | S | | | | |
| 1 | 55218885 | Service belt | | S | | S | | S | | | | |
| 1 | 55244469 | Bearing of belt tensioner services | | S | | S | | S | | | | |
| 1 | 55275618 | Tendicinghia fisso | | S | | S | | S | | | | |
| 1 | 1393294080 | Rear whee arch | L | M | | M | | M | | | | |
| 1 | 1397124080 | Rear whee arch | R | M | | M | | M | | | | |
| 1 | 1373743080 | Roof | | M | | M | | M | | | | |
| 1 | 1367185080 | Front door | R | L | | L | | L | | | | |
| 1 | 1386106080 | Front mudguard | R | L | | | | L | | | | |
| 1 | 51945969 | Front bonnet | | L | | | | L | | | | |
| 1 | 1395026080 | Front door | L | L | | | | L | | | | |
| 1 | Codice Ricambio | Diagnosi elettronica - ricerca errori | | | | | | | | | | |
| 1 | Codice Ricambio | Lavaggio impanto a.c. ~ Lavaggio meccanica | | | | | | | | | | |

New for old value (N)

Remarks

VEICOLO SPORCO, MAL STOCCATO
SPIA AVARIA MOTORE ATTIVA
PNEUMATICI BRIDGESTONE ESTIVI 195/65 R 15
COMPUTO INTEGRATO CON IL PREVENTIVO FORNITO, CORRELATO ALL UTILIZZO DEL MEZZO.



Prepared by A.M.G. Software di Torino - Ph. (011) 599.870 - Fax (011) 595.323 - www.amgsoftware.it - e-mail info@amgsoftware.it