

MACDAM

Volvo XC40 '17

Vehicle information




Make:	Volvo	License:	
Gearbox:	Automatic	Body color:	
Model:	XC40 '17	VIN:	YV1XZEDVEM2614967
Fuel type:	Electric	Power:	300 kW
Version:	XC40 P8 Recharge AWD	First registration	24/06/2021
Mileage:	202454 km	N° of doors:	

Damage summary


Front	1
Left	2
Rear	1
Right	3

Commercial pictures






Options according to the inspector				
Central consol F	Yes	GPS	Yes	Headlights Xenon/LED/Laser
Panoramic roof	Yes	Radio multimedia	Yes	Rear view camera
Sun Roof electric	Yes	Telephone equipment	Yes	

Damages	
Alloy rim FL Scratch(es) Repair and paint (complete) Left  	
Alloy rim RL Scratch(es) Repair and paint (complete) Left  	
Alloy rim RR Scratch(es) Repair and paint (complete) Right  	
Bumper F Scratch(es) Repair and paint (complete) Front  	
Charging cable (normal) Missing Replace Rear 	

Door FR
Scratch(es)
Repair and paint (complete)
Right



Door RR
Scratch(es)
Repair and paint (complete)
Right



Tyres

Front Left

Summer

255/45/19/100/V

Bridgestone

6.3 mm

Front Right

Summer

255/45/19/100/V

Bridgestone

6.1 mm

Rear Left

Summer

255/45/19/100/V

Bridgestone

5.8 mm

Rear Right

Summer

255/45/19/100/V

Bridgestone

5.8 mm

Checks

CO2 Emission	0	Digital maintenance	N/A
GPS storage	Yes	Luggage cover	Yes
Number head rests	5	Number of charging cables (rapid charge)	1
Number of keys total	3	Reset to factory settings	Yes, vehicle is reset to factory settings
Service book	Yes	User's manual	Yes

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.