

Inspection data

Inspection date **28/04/2026 13:57**

Vehicle data

Make / Type **SKODA ENYAQ**


VIN **TMBJB7NY0MF025120**

First registration date **17/06/2021**

Mileage **87.207 km**



Vehicle pictures





Tires

Location	Position	Depth	Dimension	Make	Type
Voor	Links	4,0 mm	235/45 R 21 104 T	Continental	Zomer
Voor	Rechts	3,0 mm	235/45 R 21 104 T	Continental	Zomer
Achter	Links	4,0 mm	235/45 R 21 104 T	Continental	Zomer
Achter	Rechts	5,0 mm	235/45 R 21 104 T	Continental	Zomer

Damages with pictures

Claim(s) own risk to be invoiced

Bumper V

Barst

LI - Herstellen en schilderen
(gedeeltelijk)



Velg alu V L

Kras(sen)


LI - Herstellen en schilderen
(compleet)



Velg alu A L

Kras(sen)


LI - Herstellen en schilderen
(compleet)



Velg alu V R

Kras(sen)


LI - Herstellen en schilderen
(compleet)



Velg alu A R

Kras(sen)

LI - Herstellen en schilderen
(compleet)



Not invoiced

Sierlijst bumper A

Kras(sen)

Le - Vervangen en schilderen



Sierlijst bumper V

Deuk(en)

Smartrepair



Band V R

Scheur

E - Vervangen

