



RENAULT KANGOO FURGÓN L1 1.5 Blue dCi 70kW (95CV) furgón 4P manual: 6073-MCS

Vinnnumber:	VF1RFK00870152229	Versionname:	
First Registrationdate:	5/12/2022	Fiscalpower:	0
Expertise Mileage:	43484	Power Kw:	
Bodytype:	Transporter	Body colour:	White
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Steel
Transmission:			
Fueltype:	Diesel		
Engine functioning:	Yes		
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of seats:	2		
Number head rests:	2		
Type of rims (mounted):	Steel		
Certificate of Conformity:	No		
Category:	Light Commercial Vehicle		
Registration Certificate Car (BE):	No		

Options

Number of keys total:	1	Radio:	
Number keys remote:	1		
Windows electric F:			
Cruise Control:			
Steering wheel multifunctional:			
Type of climate control:	Manual climate control		

Tyres

195/65/15/95 H				
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm
Tyre profile depth FL:				5.0
Tyre profile depth FR:				5.0
Tyre profile depth RL:				6.0
Tyre profile depth RR:				6.0
Tyre size FL:				195/65 R 15 95 H
Tyre size FR:				195/65 R 15 95 H
Tyre size RL:				195/65 R 15 95 H
Tyre size RR:				195/65 R 15 95 H
Tyre type FL:				Summer
Tyre type FR:				Summer
Tyre type RL:				Summer
Tyre type RR:				Summer
Tyre make FL:				259
Tyre make FR:				259
Tyre make RL:				259
Tyre make RR:				259

Assistance equipment

Repair kit:	No
-------------	-----------

Registration document, Missing, Repair/replace (lump sum)



User's manual, Missing, Repair/replace (lump sum)



MOT certificate, Missing, Repair/replace (lump sum)



Ignition key, Missing, Repair/replace (lump sum)



Interior, Dirty, Cleaning



Door FL, Scratch(es), Acceptable



Windscreen, Broken, Replace



Bumper F, Unclassped, Dismount/Mount



Wing FR, Scratch(es), Acceptable



Side wall RR, Dent(s) and scratch(es), Acceptable




Tyre repair kit, Missing, Repair/replace (lump sum)



Bumper corner RL, Scratch(es), Paint



Tyres, No damage, Check



Bodywork, Glue residues, Remove lettering

