DEKRA

DEKRA Automotive Solutions

Appraisal Report

Vehicle details

VIN	ZAC5JACLX RJL12428	Registration date	19/12/2024	Exterior Color	Unknown
Brand	JEEP	Licence Plate	EU-FA 8557	Odometer	18 313 km
Model	AVENGER 1.2 GSE T3 GDI Altitude				

Inspection Details

Arrival Date	20/08/2026	Inspection ID	7124068	Inspection date	25/08/2026
Assign Date	20/08/2026	Fleet owner	Leasys FINN	Inspection loc.	Leasys AKB Schöneck



Generic equipment

Removable element


Spare wheel kit	✓
Rear parcel shelf	✓
Floor mat BR	✓
Floor mat BL	✓
Floor mat FR	✓
Floor mat FL	✓

Technical Document

User manual	✓
Warranty booklet	✓
Log books	✓
Spare key	✓
Key	✓
Remote key	✓
Service	✗

Tyres

Goodyear 215/60/17 V All seasons 5.0 mm	Goodyear 215/60/17 V All seasons 5.0 mm
Goodyear 215/60/17 V All seasons 6.0 mm	Goodyear 215/60/17 V All seasons 6.0 mm





Exception / Damage

1



Part	Door	Repair Time	-	Part Cost	-
Position	Front left	Repair Cost	-	Gross Cost	-
Damages	Scratched	Paint Time	-	Depreciation %	10.00%
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	-

Summary Inspection

Gross Price	0.00€	Depreciation	-	Net Price	0.00€

Labor cost summary

	Hourly Rate	Time	Gross Price	Depreciation %	Depreciation	Net Price
Bodywork	0.00€	0.00	0.00€	-	-	0.00€
Paintwork	0.00€	0.00	0.00€	-	-	0.00€
Paint preparation	0.00€	0.00	0.00€	-	-	0.00€

Miscellaneous

	Gross Price	Depreciation %	Depreciation	Net Price
Small parts / disposal charge	0.00€	-	-	0.00€
Part Cost	0.00€	-	-	0.00€
Flat Rate	0.00€	-	-	0.00€