SCHIPPER VAASEN
AUTOMOTIVE SERVICES

Technician
Rutger Koogh

2-FLP-547

2-FLP-547 · ST Line X 1.0i EcoBoost 155pk - 114kW - Mhev A7 -Clipper - leather seats · 27 October 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FLP-547
Manufacturer	FORD
Model	Focus
Model Versions	ST Line X 1.0i EcoBoost 155pk - 114kW - Mhev A7 - Clipper - leather seats
Body Type	5 door hatchback
Color	Black
Paint Type	Metallic
Production Year	2024
KW	114

Fuel Type	Hybrid Gasoline
VIN	WF0PXXGCHPRC15983
Cylinder Capacity	999 cm3
Transmission Type	Automatisch geschakelde Transmissie
First Admission	11-06-2024
Odometer	47.769 Km
Numer Of Keys	2
Interior	Black
Number Headrests	5

Images































Accessories

- ABS
- Airbags
- Alloy wheels
- Audio System
- Automatic air conditioning
- Bluetooth car kit
- Central door locking
- Centre armrest
- Cruise control
- Electric rear windows
- Electric windows front

- Electrically adjustable driver\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\'s seat
- Electrically adjustable exterior mirrors
- Front & rear parking sensors
- Leather steering wheel
- Navigation system
- Rear view camera
- Roller cover / parcel shelf
- Seat heating
- Steering wheel multifunction
- Steeringwheel – Heated
- Windscreen – Heated

Condition

Condition exterior	Adequate
Condition interior	Adequate
Last Maintenance	Unknown
Maintenance Remarks	Accu bijladen
Previous Repairs	Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	4 mm	Goodyear	215 mm	50 mm	17 inch	All Season
Rear Left	4 mm	Goodyear	215 mm	50 mm	17 inch	All Season
Front Right	4 mm	Goodyear	215 mm	50 mm	17 inch	All Season
Rear Right	4 mm	Goodyear	215 mm	50 mm	17 inch	All Season
Spare Tire Type	Compressor					

Damages




Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Left	Scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Left	Scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Hood	Stonechipping	Acceptable	Yes





Damage Part	Damage Type	Repair Type	Acceptable
Grille	Broken	Replace	No






Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Front	Scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Alloy – Right Front	Damaged	Rim repair	No




Damage Part	Damage Type	Repair Type	Acceptable
Fender – Front Right	Small dent(s)	Restyle	No




Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Right	small dents / small scratches	Restyle / Touch-up	No






Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Rear	Scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Tailgate	Small dent(s)	Restyle	No