MACADAM









RENAULT MASTER: FC-545-HS

Vinnumber:	**VF1MA000361155335**	Versionname:	**RENAULT MASTER FG GCf Trac F3500 L2H2 dCi 110 Euro6 VU [4P] bvm 6-110CH-8cv (fourgon tÃ´IÃ©simple cabine)**
First Registrationdate:	**6/12/2018**	Fiscalpower:	
Expertise Mileage:	**120047**	Power Kw:	**81**
Bodytype:	**Transporter**	Body colour	**White**
Gearbox:	**MAN 6 VIT**	Paint type	**Opaque**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Diesel**	Type of rims (mounted)	**Steel**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**3**		
Number head rests	**3**		
Type of rims (mounted)	**Steel**		
Category	**Light Commercial Vehicle**		

Options

Number of keys total	**4**	Radio	
Number keys remote	**2**	Central consol F	
Windows electric F		Sliding door right-side	
Cruise Control		Rear view camera	
Steering wheel multifunctional		Seat cover lining	**Lining Other**
Type of climate control	**Manual climate control**		

Tyres

Summer tyres:	**225/65/16/112 R**			
	Fr.L.	**Hankook: 55%**	Fr.R.	**Hankook: 65%**
	Re.L.	**Hankook: 5%**	Re.R.	**Hankook: 10%**

Tyre profile depth FL	**4.6**
Tyre profile depth FR	**3.9**
Tyre profile depth RL	**7.7**
Tyre profile depth RR	**7.5**
Tyre size FL	**225/65 R 16 112 R**
Tyre size FR	**225/65 R 16 112 R**
Tyre size RL	**225/65 R 16 112 R**
Tyre size RR	**225/65 R 16 112 R**
Tyre type FL	**All seasons**
Tyre type FR	**All Seasons**
Tyre type RL	**All seasons**
Tyre type RR	**All Seasons**
Tyre make FL	**260**
Tyre make FR	**260**
Tyre make RL	**260**
Tyre make RR	**260**

Assistance equipment

Spare wheel	**Yes**	Jack	**Yes**

Steering wheel, Scratch(es), Replace






Air vent, mid-dashboard, Broken, Replace




Seat cover FL, Tear, Replace




Interior, Stain, Cleaning









Door seal FL, Tear, Replace




Wheel arch cover FL, Broken, Replace




Tyre FR, Out of tolerance, Replace




Wing FL, Dent(s) and scratch(es), Repair and paint (complete)





Side repeater L, Broken, Replace




Outside rear-view mirror housing L, Scratch(es), Replace




Door FL, Scratch(es), Paint




Outer sill L, Dent(s) and scratch(es), Repair and paint (complete)







Bumper F, Deformed / Strained, Replace






Side repeater R, Scratch(es), Replace





Door FR, Scratch(es), Paint





Sliding door R, Dent(s), Repair and paint (complete)







Side wall RR, Scratch(es), Paint






Rear bulkhead lining, Broken, Replace





Wheel arch RR, Dent(s) and scratch(es), Repair and paint (complete)





Sliding door panel R, Broken, Replace





Boot door lining R, Broken, Replace





Boot door lining L, Broken, Replace






Bumper corner RR, Scratch(es), Acceptable




Reflector, Broken, Replace




Rear light R, Broken, Replace




Reflector, Broken, Replace




Trunk door stop button, Missing, Replace




ALPHABET

Historique Maintenance

Immatriculation: **FC-545-HS** Date de 1ère immatriculation: **06/12/2018**

Modèle: **Renault MASTER FG GCf Trac F3500 L2H2 dCi 110 Euro6 VU [4P] bvm 6-110CH-8cv (fourgon tôlésimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
06/01/2026	110.003	AUTOMOBILES REPARATIONS NEUVES OCCASIONS	REVISION ET CLIM
	0		PLAQUETTES AR RPLT
	0		PLAQUETTES AV RPLT
	0		ADBLUE
	0		LIQUIDE DE REFROIDISSEMENT RPLT
	0		COURROIE ACCESSOIRES RPLT
14/10/2024	91.190	AUTOMOBILES REPARATIONS NEUVES OCCASIONS	PLAQUETTES AR RPLT
	0		COUPELLES AMORTISSEURS AR RPLT
	0		LAMPE RPLT
	0		AMORTISSEURS AV RPLT
20/08/2024	88.766	AUTOMOBILES REPARATIONS NEUVES OCCASIONS	DISQUES PLAQUETTES AV RPLT
19/02/2024	77.591	AUTOMOBILES REPARATIONS NEUVES OCCASIONS	BALAIS ESSUIE GLACE AV
	0		REVISION
	0		ADBLUE
	0		LAMPE CODE AVD RPLT
	0		AMORTISSEURS AR RPLT
	0		DURITE DE TURBO RPLT
	0		ECHANGEUR AIR HUILE RPLT
	0		SOUFFLET DE CARDAN RPLT
	0		DIVERS
	0		HUILE BV CTRL
22/03/2023	58.686		LIQUIDE DE FREIN
	0		BATTERIE RPLT
	0		DISQUES PLAQUETTES AR RPLT
	0		REVISION ET CLIM ET AIR ET CARBURANT
	0		DISQUES PLAQUETTES AV RPLT
20/09/2022	48.235		BALAIS ESSUIE GLACE AV
	0		PLAQUETTES AV RPLT
	0		ESSAI
	0		SOUFFLET DE CARDAN RPLT
	0		JOINT SPI DIFFERENTIEL RPLT

Historique Maintenance

Immatriculation: **FC-545-HS** Date de 1ère immatriculation: **06/12/2018**

Modèle: **Renault MASTER FG GCf Trac F3500 L2H2 dCi 110 Euro6 VU [4P] bvm 6-110CH-8cv (fourgon tôlésimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
	0		AMORTISSEURS AV RPLT
	0		PLAQUETTES AR RPLT
11/03/2021	29.048		ADBLUE
	0		REVISION ET CLIM
14/12/2020	26.321		PLAQUETTES AV RPLT
	0		PLAQUETTES AR RPLT
	0		BALAIS ESSUIE GLACE AV