



HYUNDAI TUCSON: GL-608-EJ

Vinnumber:	TMAJC81AGNJ259580	Versionname:	HYUNDAI TUCSON 1.6 CRDI 136 DCT-7 HYBRID 48V BUSINESS VP [5P] bva 7-136CH-7cv (SUV)
First Registrationdate:	19/12/2022	Fiscalpower:	
Expertise Mileage:	68550	Power Kw:	100
Bodytype:	Off-road	Body colour:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Interior colour:	Anthraccite
Fueltype:	Hybrid	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Anthraccite
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Windows electric R		Rear parking sensors	
Cruise Control		Rear view camera	
Steering wheel multifunctional		Seat cover lining	Lining Other
Steering wheel leather			
Type of climate control	Autom climate control		

Tyres

	215/65/17/103 V			
Summer tyres:	Fr.L.	Michelin: 95%	Fr.R.	Michelin: 100%
	Re.L.	Michelin: 80%	Re.R.	Michelin: 85%
Tyre profile depth FL				1.8
Tyre profile depth FR				1.1
Tyre profile depth RL				3.1
Tyre profile depth RR				2.4
Tyre size FL				215/65 R 17 103 V
Tyre size FR				215/65 R 17 103 V
Tyre size RL				215/65 R 17 103 V
Tyre size RR				215/65 R 17 103 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Interior, Stain, Cleaning





Remote ignition key, Missing, Repair/replace (lump sum)



Roof liner, Unclipped, Dismount/Mount



Tyre FL, Out of tolerance, Replace



Tyre RL, Out of tolerance, Replace



Tyre RR, Out of tolerance, Replace



Tyre FR, Out of tolerance, Replace



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Side repeater L, Broken, Replace



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Door trim RL, Scratch(es), Acceptable



Bumper F, Scratch(es), Paint



Bumper spoiler F, Scratch(es), Acceptable



Bonnet, Scratch(es), Polish



Wing RR, Scratch(es), Polish



Door RR, Scratch(es), Polish



Wing trim FR, Scratch(es), Replace



Wing FR, Scratch(es), Paint



Rear roof pillar covering L, Scratch(es), Replace



Rubber seal for boot lid, Tear, Replace



Tailgate / Boot, Dent(s) and scratch(es), Repair and paint (complete)



Historique Maintenance

Immatriculation: **GL-608-EJ** Date de 1ère immatriculation: **19/12/2022**
Modèle: **Hyundai TUCSON 1.6 CRDI 136 DCT-7 HYBRID 48V BUSINESS VP [5P] bva 7-136CH-7cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
04/09/2025	55.296	AUTODIF	LIQUIDE DE FREIN
	0		BALAIS ESSUIE GLACE AV AR
	0		REVISION ET CLIM ET AIR ET CARBURANT
13/08/2024	34.029	CONTITRADE FRANCE	REMPLACEMENT PNEUS ETE
29/07/2024	25.559	EUROFLEET TYRES AND SERVICES	CHAINES NEIGE RPLT
23/04/2024	25.559	MAUREL AUDOISE	REPARATION DE ROUE
03/04/2024	23.592	AUTODIF	LIQUIDE DE FREIN
	0		REVISION ET CLIM