SCHIPPER VAASEN
AUTOMOTIVE SERVICES

Technician
Bas Vaasen

# 2-FXL-851

2-FXL-851 · Cross 1.8 Hybrid Safety Pack DYNAMIC 1.8 140PS AT / · 4 November 2026 · Zaventem Brussel

## Specifications

| | |
|---|---|
| License Plate Number | 2-FXL-851 |
| Manufacturer | TOYOTA |
| Model | Corolla Cross |
| Model Versions | Cross 1.8 Hybrid Safety Pack DYNAMIC 1.8 140PS AT / |
| Body Type | 5 door hatchback |
| Color | Grey |
| Paint Type | Metallic |
| Production Year | 2024 |
| KW | 103 |
| Fuel Type | Hybrid Gasoline |

| | |
|---|---|
| VIN | JTNADADB10J020354 |
| Cylinder Capacity | 1.798 cm3 |
| Transmission Type | Automatisch geschakelde Transmissie |
| First Admission | 26-09-2024 |
| First Registration | 26-09-2024 |
| Odometer | 63.388 Km |
| Numer Of Keys | 2 |
| Interior | Black – Cloth |
| Number Headrests | 5 |

## Images































## Accessories

| | |
|---|---|
| ABS | Cruise control |
| Airbags | Electric rear windows |
| Alloy wheels | Electric windows front |
| ASR | Electrically adjustable exterior mirrors |
| Audio System | Leather steering wheel |
| Automatic air conditioning | Parking sensors |
| Bluetooth car kit | Rear view camera |
| Central door locking | Roller cover / parcel shelf |
| Centre armrest | Steering wheel multifunction |

## Condition

| | | | |
|---|---|---|---|
| Condition exterior | Adequate | Last Maintenance | Unknown |
| Condition interior | Adequate | Previous Repairs | Unknown |

## Tire Specifications

| Tire | Profile | Brand | Width | Aspect Ratio | Radial | Type |
|---|---|---|---|---|---|---|
| Front Left | 2 mm | UniRoyal | 215 mm | 55 mm | 17 inch | All Season |
| Rear Left | 4 mm | Hankook | 215 mm | 55 mm | 17 inch | All Season |
| Front Right | 2 mm | UniRoyal | 215 mm | 55 mm | 17 inch | All Season |
| Rear Right | 4 mm | Hankook | 215 mm | 55 mm | 17 inch | All Season |
| Spare Tire Type | Homecomer | | | | | |

## Damages




| Damage Part | Damage Type | Repair Type | Acceptable |
|---|---|---|---|
| Frontdoor – Left | Small dent(s) | Restyle | No |






| Damage Part | Damage Type | Repair Type | Acceptable |
|---|---|---|---|
| spoiler RB | Small scratch(es) | Plastic Repair | No |




| Damage Part | Damage Type | Repair Type | Acceptable |
|---|---|---|---|
| Fender – Rear Left | Small dent(s) | Restyle | No |




| Damage Part | Damage Type | Notes | Repair Type | Acceptable |
|---|---|---|---|---|
| Co drivers seat | Burned | meerdere gaatjes | Replace | No |