MACADAM










Cupra Born: N902SB

Vinnumber:	**VSSZZZK1ZNP003305**	Versionname:	**Born 150kW/62kWh Copper Edition One automaat**
First Registrationdate:	**24/12/2021**	Fiscalpower:	
Expertise Mileage:	**113185**	Power Kw:	**150**
Bodytype:		Body colour	**Exclusieve lak Aurora Blue**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:		Type of rims (mounted)	**Aluminium**
Fueltype:	**Electric**	Parking lot	**859**
Number of seats	**5**		
Type of rims (mounted)	**Aluminium**		
Maintenance needed	**Yes**		

Options

Number of keys total	**2**	Lining semi-leather	
GPS		Lining Alcantara	
Autom climate control		Panoramic roof	
Radio multimedia		Rear parking sensors	
		Rear view camera	

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	215 / 45 / 20 / 95 / T / Aluminium	7,1 mm	Continental	All season
	Right	215 / 45 / 20 / 95 / T / Aluminium	8,0 mm	Continental	All season
Rear	Left	215 / 45 / 20 / 95 / T / Aluminium	6,5 mm	Continental	All season
	Right	215 / 45 / 20 / 95 / T / Aluminium	7,2 mm	Continental	All season

Assistance equipment

Number of charging cables (rapid charge)	**1**

Service, Maintenance, Execute



Malfunction, Not functioning (well), Diagnosis



Door FL, Scratch(es), Repair and paint (complete)






Door RL, Scratch(es), Repair and paint (complete)





Bonnet, Chemical polution, Polish

Bumper F, Scratch(es), Repair and paint (complete)








Wing RR, Scratch(es), Repair and paint (complete)






Roof pillar R, Dent(s), Repair and paint (complete)





Wing FR, Scratch(es), Repair and paint (complete)






Door FR, Scratch(es), Repair and paint (complete)




Outside rear-view mirror housing R, Scratch(es), Polish




Bumper R, Crack, Repair and paint (complete)







Bumper RM, Scratch(es), Repair and paint (complete)






Tailgate / Boot, Scratch(es), Polish





Rear window, Scratch(es), Replace





Onderhoudshistorie van: VSSZZZK1ZNP003305

ALPHABET

Kenteken	N902SB
Merk Model	Cupra Born 150kW/62kWh Copper Edition One automaat
Brandstofsoort	Elektrisch
Datum deel1	12/24/21

Datum reparatie	Kilometerstand	Reparatie omschrijving
10/30/25	96,370	APK
10/30/25	96,370	Vervanging band
3/20/25	0	Accu
10/7/24	70,372	Onderhoudsbeurt
10/7/24	70,372	Remvloeistof
10/7/24	70,372	Ruitenwisserblad(en) voorzijde
9/8/22	22,070	Vervanging band