

Vehicle details

VIN	KMHCH851JF NU085957	Brand	HYUNDAI	Maintenance date	01/01/1900
Licence Plate		Model	Ioniq EV Comfort 5d	Maintenance mileage	-
Registration date	28/01/2022	Year	2022	Exterior Color	Silver Metallic
Odometer	135 107 km	Engine size	-	interior Color	Grey
Fuel	Electric	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details




Generic equipment	
Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element	
Spare wheel kit	✓
Load cover	✓
Vehicle charger	✓
Wireless charger	✓

Technical Document	
User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Yokohama 205/60/16 Summer 4.0 mm



Yokohama 205/60/16 Summer 4.0 mm



Michelin 205/60/16 Summer 4.5 mm

Michelin 205/60/16 Summer 4.5 mm

Exterior

2



Part	Step plate
Position	Back left
Damages	Dent & Chips
Severity	-
Repair mode	For info

3



Part	Door
Position	Back left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

5



Part	Sill
Position	Left
Damages	Scratched
Severity	-
Repair mode	Repair

8



Part	Wing
Position	Back left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

9



Part	Spray Suppressor
Position	Front left
Damages	Dent & Chips
Severity	-
Repair mode	For info

10



Part	Door
Position	Front right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

11



Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Repair


Interior damage

1



Part	Interior tailgate lining
Position	-
Damages	Scratched
Severity	-
Repair mode	For info

4





Part	Other interior
Position	-
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning
Geroookt in voertuig	

6



Part	Interior cleaning
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

7  	Part	Interior cleaning
	Position	Front
	Damages	Stained/dirty
	Severity	-
	Repair mode	Cleaning

Comments