

INSPECTION REPORT


End of contract

GENERAL INFO

File	316181
License plate	2DEC184
Vehicle identification number	SB1Z93BE10E332074
Dossier	2022054102
Make	Toyota Corolla TS 1.8 Hybrid P
Mileage	156410
First registration	20/02/2023
client availability date	29/06/2026
inspectionDate	15/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
801	See External Expertise	N
891	Lettering Removal 15min	N
13	Bumper Front // Painting	N
33	Front Bonnet // Repair & Painting	Y
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	Y
99	Rocker Panel Left / Cover / Replace & Painting	N
100	Door Rear Left // Smart Repair Small	Y
110	Wing Rear Left // Smart Repair Small	Y
134	Bumper Rear // Repair & Painting	N
159	Rear Bonnet / Rear Window / Replace	Y
169	Rear Bonnet / Spoiler / Replace & Painting	Y
183	Wing Rear Right // Painting	Y
190	Door Rear Right // Smart Repair Small	Y
201	Rocker Panel Right // Smart Repair Medium	Y
202	Rocker Panel Right // Painting	N
210	Door Front Right // Smart Repair Small	Y
213	Door Front Right // Painting	N
274	Bumper Front / Grid Central / Replace	N
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
532	Trunk Compartment / Side Cover Left / Replace	Y
533	Trunk Compartment / Side Cover Right / Replace	Y
539	Trunk Compartment / Back Coating / Replace	Y
564	Dashboard // Replace Completely	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
644	Rear Right Door Interior Coating // Replace Completely	Y
860	Interior Cleaning // Small	N

Damage Pictures




Trunk Compartment / Back Coating / Replace-bad position



Rocker Panel Right // Smart Repair Medium-dent



Rocker Panel Left // Smart Repair Medium-dent



Door Rear Left // Smart Repair Small-dent



Front Bonnet // Repair & Painting-scratch + dent




Bumper Rear // Repair & Painting-scratch + dent



Rocker Panel Left / Cover / Replace & Painting-scratch + dent




Bumper Front / Grid Central / Replace-cracked



Interior Cleaning // Small-stain



Rear Bonnet / Spoiler / Replace & Painting-scratch



Rear Bonnet / Rear Window / Replace-scratch



Door Front Right // Smart Repair Small-scratch



Trunk Compartment / Side Cover Right / Replace-scratch



Trunk Compartment / Side Cover Left / Replace-scratch



Rear Right Door Interior Coating // Replace Completely-scratch



Dashboard // Replace Completely-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Wing Rear Right // Painting-scratch



Door Rear Right // Smart Repair Small-scratch



Door Front Right // Painting-scratch



Wheel Two Tone Rear Right // Repair-scratch



Wheel Two Tone Front Right // Repair-scratch



Bumper Front // Painting-scratch




Wheel Two Tone Front Left // Repair-scratch




Door Front Left // Smart Repair Small-scratch



Wheel Two Tone Rear Left // Repair-scratch




Rocker Panel Right // Painting-scratch



Wing Rear Left // Smart Repair Small-dent



Lettering Removal 15min-Remainder stickers



See External Expertise-dent