French

DEKRA

Volvo

XC60 B4 MHEV PLUS

VIN: YV1UZK5V0P1332431

PDF

Estim
refurbishm

21:



Description

Registration number

Registration date
11/04/2023

Odometer
87280 km

Model year
-

Color
Black

Box type
-

Vehicle equipment

Rear view camera
Automatic air conditioning
Alloy wheels
Rear proximity radar
Front proximity radar
Cruise control
Heated upholstery
Electrically adjustable upholstery
Navigation system
Sunroof

Additional costs

Total additiona

Name	N
Painting preparation costs	

Total ac

Inspection Details

Date of inspection
07/05/2025

Inspection validation date
05/09/2025

Damages and corrections

Element	Position	Damage	Correction
Tire Rim/Tire Diameter: 19	Front Left	Worn	Exchange
Rim Material: Aluminum alloy / Rim/Tire diameter: 19	Left Back	Stripe	Acceptable (for the record)
Tire Rim/Tire Diameter: 19	Right Back	Torn	Exchange
Rim Material: Aluminum alloy / Rim/Tire diameter: 19	Right Back	Stripe	Paint
Tire Rim/Tire Diameter: 19	Front Right	Torn	Exchange
Rim Material: Aluminum alloy / Rim/Tire diameter: 19	Front Right	Stripe	Paint
Bumper	Before	Sinking	Repair

Element	Position	Damage	Correction
Bumper strip	Front Left	Stripe	Polishing
Bumper grille	Before	Stripe	Paint
Wing	Front Left	Sinking	Acceptable (for the record)
Windshield	-	Broken	Exchange

Removable elements

Slow charging cable	Fast charging cable	Luggage cover
Warranty booklet	Memory card	Anti-theft key
Flip key	Compressor pneumatic repair kit	Jack
User Manual	Rear beach	Tire repair kit refill
Spare wheel		

Main tires

Front Left	MICHELIN	235 / 55 / 19 / All	1.5 mm
Front Right	MICHELIN	235 / 55 / 19 / All	3 mm
Left Back	MICHELIN	235 / 55 / 19 / All	5 mm
Right Back	MICHELIN	235 / 55 / 19 / All	4.5 mm
Back		/ / /	7 mm