



**Mazda 3:**

Vinnumber:	<b>JM4BP6HE601209914</b>	Versionname:	
First Registrationdate:	<b>9/06/2021</b>	Fiscalpower:	
Expertise Mileage:	<b>126172</b>	Power Kw:	
Bodytype:		Body colour:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:		Parking lot:	<b>1214</b>
Fueltype:	<b>Hybrid Petrol</b>		
Maintenance:	<b>NOT OK</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		
Registration Certificate Home (BE):	<b>No</b>		

**Options**

Number of keys total:	<b>2</b>	Front parking sensors:	
Cruise Control:		Rear parking sensors:	
Steering wheel multifunctional:		Type of Tow bar:	<b>Tow bar removable</b>
Seats F heated:			
Radio multimedia:			
Type of headlighting:	<b>Headlighting LED</b>		
Type of GPS:	<b>GPS big screen color</b>		
Type of Lining:	<b>Lining fabrics</b>		
Type of climate control:	<b>Autom climate control</b>		
Head-up Display:			

**Limited Technical Inspection**

**Tyres**

<b>215/45/18/99 W</b>				
Summer tyres:	Fr.L.	<b>Toyo: 4 mm</b>	Fr.R.	<b>Toyo: 4 mm</b>
	Re.L.	<b>Toyo: 4 mm</b>	Re.R.	<b>Toyo: 4 mm</b>
Tyre profile depth FL				<b>4.0</b>
Tyre profile depth FR				<b>4.0</b>
Tyre profile depth RL				<b>4.0</b>
Tyre profile depth RR				<b>4.0</b>
Tyre size FL				<b>215/45 R 18 99 W</b>
Tyre size FR				<b>215/45 R 18 99 W</b>
Tyre size RL				<b>215/45 R 18 99 W</b>
Tyre size RR				<b>215/45 R 18 99 W</b>
Tyre type FL				<b>Summer</b>
Tyre type FR				<b>Summer</b>
Tyre type RL				<b>Summer</b>
Tyre type RR				<b>Summer</b>
Tyre make FL				<b>2483</b>
Tyre make FR				<b>2483</b>
Tyre make RL				<b>2483</b>
Tyre make RR				<b>2483</b>

**Assistance equipment**

Repair kit:	<b>Yes</b>	Compressor:	<b>Yes</b>
Number of charging cables (normal):	<b>0</b>		
Number of charging cables (rapid charge):	<b>0</b>		

Total cost ex VAT:	<b>228,50</b>
Service, Maintenance, Check:	<b>0,00</b>



Bonnet, Dent(s) and scratch(es), Acceptable 0,00



Alloy rim FL, Scratch(es), Repair and paint (complete) 133,03



Door RL, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Acceptable 0,00




Alloy rim FR, Scratch(es), Acceptable 0,00



Door FR, Dent(s), Acceptable 0,00



Wing RR, Dent(s), Paintless dent repair 95,47



Roof, Hail damage, Repair and paint (complete) 0,00



