



DS 7 CROSSBACK: GA-036-PF

Vinnumber:	VR1J4DGZUMY514574	Versionname:	DS DS 7 CROSSBACK E-TENSE 225 RIVOLI VP [5P] bva 8-225CH-10cv (SUV)
First Registrationdate:	6/07/2021	Fiscalpower:	
Expertise Mileage:	58560	Power Kw:	165
Bodytype:	SUV	Body colour:	Dark Blue
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Plug-in hybrid	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Radio	
Number keys remote	2	Seats electric F L	
GPS big screen color		Seats electric F R	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Headlights Xenon/LED/Laser	
Steering wheel multifunctional		Front parking sensors	
Steering wheel leather		Rear parking sensors	
Type of climate control	Autom climate control	Rear view camera	
		Seat cover lining	Lining Leather

Tyres

	235/50/19/103 V			
Summer tyres:	Fr.L.	Michelin: 70%	Fr.R.	Michelin: 60%
	Re.L.	Michelin: 55%	Re.R.	Michelin: 65%
Tyre profile depth FL	3.7			
Tyre profile depth FR	4.4			
Tyre profile depth RL	4.7			
Tyre profile depth RR	4.0			
Tyre size FL	235/50 R 19 103 V			
Tyre size FR	235/50 R 19 103 V			
Tyre size RL	235/50 R 19 103 V			
Tyre size RR	235/50 R 19 103 V			
Tyre type FL	Summer			
Tyre type FR	Summer			
Tyre type RL	Summer			
Tyre type RR	Summer			
Tyre make FL	261			
Tyre make FR	261			
Tyre make RL	261			
Tyre make RR	261			

Assistance equipment

Tyre RR, Out of tolerance, Replace



Tyre FL, Out of tolerance, Replace



Alloy rim RL bitone/polychrome, Scratch(es), Repair/replace (lump sum)




Alloy rim RR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Side repeater L, Scratch(es), Replace



Door FL, Scratch(es), Paint



Bumper moulding F, Scratch(es), Acceptable



Side repeater R, Broken, Replace



Outside rear-view mirror housing R, Scratch(es), Paint



Door FR, Dent(s), Repair and paint (complete)



Bumper R, Scratch(es), Paint



Tailgate / Boot, Stone chip(s), Paint



Historique Maintenance

Immatriculation: **GA-036-PF** Date de 1ère immatriculation: **06/07/2021**

Modèle: **DS 7 CROSSBACK E-TENSE 225 RIVOLI VP [5P] bva 8-225CH-10cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
07/11/2025	54.945	TRUJAS PARIS EST	BATTERIE RPLT
	0		DIVERS ELEC
12/08/2025	51.748	ACO SECURITE	CONTROLE TECHNIQUE
25/06/2025	48.583	STELLANTIS &YOU FRANCE SAS	BATTERIE RPLT
	0		LIQUIDE DE FREIN
	0		REVISION ET CLIM ET AIR ET BOUGIES
	0		DIVERS CLIM
26/06/2024	36.000	STELLANTIS &YOU FRANCE SAS	BALAIS ESSUIE GLACE AV
	0		REVISION
08/07/2022	12.560	STELLANTIS &YOU FRANCE SAS	REVISION