MACADAM








ALFA ROMEO Stelvio: 7057-MKM

Vinnumber:	**ZARPAGPX7P7D74025**	Versionname:	**2.2 Diesel 118kW (160CV) SPRINT RWD todoterreno 118kW 5P automática**
First Registrationdate:	**26/09/2023**	Fiscalpower:	
Expertise Mileage:	**84064**	Power Kw:	
Bodytype:	**SUV**	Body colour	**Grey**
Gearbox:	**Automatic**	Type of rims (mounted)	**Aluminium**
Transmission:			
Fueltype:	**Diesel**		
Engine functioning	**Yes**		
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**1**	Central consol F	
Number keys remote	**1**	Luggage cover	
GPS big screen color		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Steering wheel leather			
Radio multimedia			
Type of climate control	**Autom climate control**		

Tyres

Summer tyres:	**235/55/19/105 W**			
	Fr.L.	**Pirelli: 4 mm**	Fr.R.	**Pirelli: 4 mm**
	Re.L.	**Continental: 4 mm**	Re.R.	**Continental: 4 mm**

Tyre profile depth FL	**4.0**
Tyre profile depth FR	**4.0**
Tyre profile depth RL	**4.0**
Tyre profile depth RR	**4.0**
Tyre size FL	**235/55 R 19 105 W**
Tyre size FR	**235/55 R 19 105 W**
Tyre size RL	**235/55 R 19 105 W**
Tyre size RR	**235/55 R 19 105 W**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**264**
Tyre make FR	**264**
Tyre make RL	**256**
Tyre make RR	**256**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**

Boot lid covering R, Scratch(es), Repair/replace (lump sum)




Ignition key, Missing, Repair/replace (lump sum)




Fender moulding FL, Scratch(es), Repair and paint (complete)




Wing FL, Scratch(es), Repair and paint (complete)




Door FL, Scratch(es), Repair and paint (complete)




Wing RL, Dent(s), Repair and paint (complete)




Door RL, Scratch(es), Repair and paint (complete)




Fender moulding RL, Scratch(es), Repair and paint (complete)




Bumper F, Scratch(es), Repair and paint (complete)




Wing RR, Scratch(es), Repair and paint (complete)




Door RR, Scratch(es), Repair and paint (complete)




Door FR, Scratch(es), Repair and paint (complete)




Wing FR, Scratch(es), Repair and paint (complete)




Bumper R, Scratch(es), Repair and paint (complete)




Tyres, No damage, Check








