MACADAM









DS 7: GQ-846-YK

Vinnumber:	**VR1JCYHZUPY598500**	Versionname:	**DS DS 7 BlueHDi 130 Automatique BASTILLE VP [5P] bva 8-130CH-7cv (SUV)**
First Registrationdate:	**30/08/2023**	Fiscalpower:	
Expertise Mileage:	**130835**	Power Kw:	**96**
Bodytype:	**SUV**	Body colour	**Grey**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Diesel**	Type of rims (mounted)	**Aluminium**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Category	**Passenger Car**		

Options

Number of keys total	**1**	Radio	
Number keys remote	**1**	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Seat cover lining	**Lining Other**
Steering wheel leather			
Type of climate control	**Autom climate control**		

Tyres

Summer tyres:	**225/55/18/102 V**			
	Fr.L.	**Michelin: 80%**	Fr.R.	**Michelin: 75%**
	Re.L.	**Pirelli: 40%**	Re.R.	**Pirelli: 35%**

Tyre profile depth FL	**3.1**
Tyre profile depth FR	**3.4**
Tyre profile depth RL	**5.7**
Tyre profile depth RR	**5.9**
Tyre size FL	**225/55 R 18 102 V**
Tyre size FR	**225/55 R 18 102 V**
Tyre size RL	**225/55 R 18 102 V**
Tyre size RR	**225/55 R 18 102 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**261**
Tyre make FR	**261**
Tyre make RL	**264**
Tyre make RR	**264**

Assistance equipment

Seat cover RR, Tear, Repair/replace (lump sum)




Seat cover FR, Stain, Cleaning




Seat cover FL, Stain, Cleaning




Floor mat F, Burned, Replace










Remote ignition key (no insert), Missing, Repair/replace (lump sum)



Tyre FL, Out of tolerance, Replace




Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)











Alloy rim RR bitone/polychrome, Scratch(es), Repair/replace (lump sum)





Tyre FR, Out of tolerance, Replace




Alloy rim FR bitone/polychrome, Scratch(es), Acceptable





Door RL, Dent(s) and scratch(es), Repair and paint (complete)






Bumper spoiler F, Scratch(es), Acceptable




Wing RR, Dent(s), Acceptable





Door trim RR, Scratch(es), Replace




Door trim FR, Scratch(es), Replace




Bumper R, Scratch(es), Paint




ALPHABET

Historique Maintenance

Immatriculation: **GQ-846-YK** Date de 1ère immatriculation: **30/08/2023**

Modèle: **DS 7 BlueHDi 130 Automatique BASTILLE VP [5P] bva 8-130CH-7cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
09/06/2026	118.985	FLEET SOLUTIONS FRANCE	FILTRE A AIR RPLT
			REVISION
			FILTRE A CARBURANT RPLT
			FILTRE CLIM RPLT
13/05/2026	115.731	FLEET SOLUTIONS FRANCE	PERMUTATIONS PNEUS
			PERMUTATIONS PNEUS
			PERMUTATIONS PNEUS
			PERMUTATIONS PNEUS
19/01/2026	100.698	STELLANTIS &YOU FRANCE SAS	REVISION
			RECYCLAGE
18/11/2025	92.753	FLEET SOLUTIONS FRANCE	PERMUTATIONS PNEUS
07/07/2025	80.001	FLEET SOLUTIONS FRANCE	PERMUTATIONS PNEUS
			REMPLACEMENT PNEUS ETE
25/06/2025	78.828	STELLANTIS &YOU FRANCE SAS	REVISION
			BALAIS ESSUIE GLACE AV
			RECYCLAGE
			REVISION
			LIQUIDE DE FREIN
			FILTRE A AIR RPLT
			FILTRE CLIM RPLT
03/12/2024	59.604	STELLANTIS &YOU FRANCE SAS	BALAI ESSUIE GLACE AR
			REVISION
			DISQUES PLAQUETTES AV RPLT
			PLAQUETTES AR RPLT
			RECYCLAGE
			BALAIS ESSUIE GLACE AV
18/10/2024	48.755	FLEET SOLUTIONS FRANCE	PERMUTATIONS PNEUS
22/05/2024	33.984	STELLANTIS &YOU FRANCE SAS	REVISION
			ADBLUE
18/05/2024	29.224	FLEET SOLUTIONS FRANCE	PERMUTATIONS PNEUS
08/03/2024	23.596	STELLANTIS &YOU FRANCE SAS	REVISION
19/01/2024	15.960	FLEET SOLUTIONS FRANCE	REMPLACEMENT PNEUS HIVER