



Volkswagen Touran (UKL): 2APN427

Vinnumber:	WVGZZZ1TZW033447	Versionname:	Touran Highline 1.5TSi 150pk/cv 5p
First Registrationdate:	3/06/2021	Fiscalpower:	
Expertise Mileage:	132014	Power Kw:	110
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	24400.0		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar collapsible
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

205/60/16/96 V				
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Pirelli: 4 mm	Re.R.	Pirelli: 3 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				3.0
Tyre size FL				205/60 R 16 96 V
Tyre size FR				205/60 R 16 96 V
Tyre size RL				205/60 R 16 96 V
Tyre size RR				205/60 R 16 96 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				264
Tyre make RR				264

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Glove box, Scratch(es), Acceptable



Engine insulation, Damaged, Replace



Bumper F, Scratch(es), Acceptable



Alloy rim FL, Scratch(es), Acceptable




Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Acceptable



Step L, Dent(s) and scratch(es), Acceptable



Bumper R, Scratch(es), Acceptable




Tailgate / Boot, Dent(s) and scratch(es), Acceptable



Step R, Dent(s), Acceptable



Alloy rim FR, Scratch(es), Acceptable



Door RR, Scratch(es), Acceptable



Kenteken	2APN427
Merk Model	Volkswagen Touran Highline 1.5TSi 150pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	6/3/21

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
5/18/26	129,956	diagnose	Uitvoeren
5/18/26	129,956	inlaatspruitstuk	
5/18/26	129,956	klein materiaal	
3/19/26	126,419	bougie	Vervangen
3/19/26	126,419	diagnose	Uitvoeren
3/19/26	126,419	Inspectie met olie vervanging (vast in	Uitvoeren
3/19/26	126,419	klein materiaal	
3/19/26	126,419	luchtfILTER interieur	Vervangen
3/19/26	126,419	remschijven en blokken achter	Vervangen
3/19/26	126,419	remvloeistof	Vervangen
3/19/26	126,419	ruitensproeier	Vervangen
3/19/26	126,419	ruitensproeier	Bijvullen/-laden
3/20/25	90,412	klein materiaal	
3/20/25	90,412	luchtfILTER	Vervangen
3/20/25	90,412	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
3/20/25	90,412	remblokken vooraan	Vervangen
3/20/25	90,412	ruitensproeier	Reinigen
1/31/24	63,417	bougie	Vervangen
1/31/24	63,417	klein materiaal	
1/31/24	63,417	luchtfILTER interieur	Vervangen
1/31/24	63,417	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
1/31/24	63,417	remblokken achter	Vervangen
1/31/24	63,417	remvloeistof	Vervangen
1/31/24	63,417	zekering	Vervangen
10/6/22	31,256	Inspectie met olie vervanging (vast in	Uitvoeren
10/6/22	31,256	klein materiaal	Uitvoeren
10/6/22	31,256	ruitensproeier	Vervangen
10/6/22	31,256	ruitensproeier	Vervangen