

MACADAM



Hyundai Tucson:

Vinnumber:	TMAJD811BPJ249658	Versionname:	
First Registrationdate:	11/12/2023	Fiscalpower:	
Expertise Mileage:	178316	Power Kw:	
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	3433
Fueltype:	Hybrid Petrol		
Maintenance:	NOT OK		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Radio multimedia:		Type of Tow bar:	No Tow bar
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining fabrics		
Type of climate control:	Autom climate control		
Type of GPS storage:	HD		

Limited Technical Inspection


Tyres

215/65/17/99 V				
Summer tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Michelin: 2 mm	Re.R.	Michelin: 2 mm
Tyre profile depth FL				7.0
Tyre profile depth FR				7.0
Tyre profile depth RL				2.0
Tyre profile depth RR				2.0
Tyre size FL				215/65 R 17 99 V
Tyre size FR				215/65 R 17 99 V
Tyre size RL				215/65 R 17 99 V
Tyre size RR				215/65 R 17 99 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT	797,89
Service, Maintenance, Check	0,00



Seat cover R, Stain, Cleaning 29,16



Door panel RR, Scratch(es), Replace 387,02



Shutter / cover F, Deformed / Strained, Acceptable 0,00



Bonnet, Stone chip(s), Acceptable 0,00



Wing RL, Scratch(es), Repair and paint (complete) 0,00



Door RL, Scratch(es), Acceptable 0,00



Central pillar L, Scratch(es), Spot repair 148,33



Alloy rim FL polished, Scratch(es), Acceptable 0,00



Internal boot lining L, Scratch(es), Smart repair 116,69



Internal boot lining R, Scratch(es), Smart repair 116,69



Boot lid covering R, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Repair and paint (complete) 0,00



Central pillar R, Scratch(es), Acceptable 0,00



Outside rear-view mirror housing R, Scratch(es), Acceptable 0,00



Roof, Scratch(es), Acceptable 0,00



Bodywork, Not original part, Remove lettering 0,00

