



BMW X1: [REDACTED]

Vinnumber:	WBA31AC0705V33846	Versionname:	
First Registrationdate:	29/04/2022	Fiscalpower:	
Expertise Mileage:	105331	Power Kw:	
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2332
Fueltype:	Diesel		
Maintenance:	OK		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Sun Roof electric	
Cruise Control:		Panoramic roof	
Steering wheel multifunctional:		Luggage cover	
Radio multimedia:		Front parking sensors	
Type of headlighting:	Headlighting Halogen	Rear parking sensors	
Type of GPS:	GPS big screen color	Type of Tow bar:	No Tow bar
Type of Lining:	Lining leather		
Type of climate control:	Autom climate control		
Type of GPS storage:	HD		

Limited Technical Inspection

Tyres

225/55/17/101 W				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				225/55 R 17 101 W
Tyre size FR				225/55 R 17 101 W
Tyre size RL				225/55 R 17 97 W
Tyre size RR				225/55 R 17 97 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Emergency spare wheel:	Yes	Jack:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT:	826,54
Seat cover FL, Worn, Acceptable:	0,00



Door panel FL, Scratch(es), Acceptable 0,00



Bumper F, Scratch(es), Repair and paint (complete) 296,58




Bumper spoiler F, Scratch(es), Smart repair 116,69



Door FL, Scratch(es), Acceptable 0,00



Door RL, Scratch(es), Acceptable 0,00



Alloy rim RL, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Repair and paint (complete) 296,58



Boot lid covering R, Scratch(es), Acceptable 0,00



Bumper trim R, Scratch(es), Smart repair 116,69



Wheel aperture RL, Scratch(es), Acceptable 0,00



Wing RR, Scratch(es), Acceptable 0,00



Wing trim RR, Scratch(es), Acceptable 0,00



Door FR, Scratch(es), Acceptable 0,00



Wing FR, Dent(s), Acceptable 0,00



Alloy rim FR, Scratch(es), Acceptable 0,00

