



HYUNDAI IONIQ: 3541-LYC

Vinnumber:	KMHC851CGNU288992	Versionname:	1.6 GDI HEV Tecno DCT berlina con portón 104kW 5P automática
First Registrationdate:	25/05/2022	Fiscalpower:	
Expertise Mileage:	208547	Power Kw:	
Bodytype:	Berline	Body colour	Dark Blue
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:			
Fueltype:	Hybrid		
Engine functioning	Yes		
Battery functioning	Yes		
Vehicle running	Yes		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	No		

Options

Number of keys total	2	Radio
Number keys remote	2	Seats electric F L
GPS big screen color		Luggage cover
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Steering wheel leather		
Radio multimedia		
Type of climate control	Autom climate control	

Tyres

	225/45/17/91 W			
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/45 R 17 91 W
Tyre size FR				225/45 R 17 91 W
Tyre size RL				225/45 R 17 91 W
Tyre size RR				225/45 R 17 91 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Spare wheel	Yes	Jack	Yes
Door panel RL, Scratch(es), Replace			



Seat cover FL, Hole, Replace



Interior, Dirty, Cleaning




Registration document, Missing, Repair/replace (lump sum)




Alloy rim FL, Scratch(es), Repair/replace (lump sum)



Door FL, Scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Bumper spoiler F, Scratch(es), Paint



Alloy rim FR, Scratch(es), Repair/replace (lump sum)



Door trim FR, Scratch(es), Repair and paint (complete)



Door trim RR, Scratch(es), Repair and paint (complete)



Door RR, Dent(s), Repair and paint (complete)



Alloy rim RR, Scratch(es), Repair/replace (lump sum)



Wing RR, Dent(s), Acceptable



Bumper R, Scratch(es), Acceptable



Bumper moulding RM, Scratch(es), Repair and paint (complete)



Internal boot lining R, Scratch(es), Replace



Tyres, No damage, Check

