



BMW 218: T171JN

Vinnumber:	WBA21BX0507M97123	Versionname:	218iA 100kW Active Tourer DCT
First Registrationdate:	30/06/2023	Fiscalpower:	
Expertise Mileage:	167364	Power Kw:	100
Bodytype:		Body colour	Sparkling Copper Grau
Gearbox:	Automatic	Paint type	Metallic
Transmission:		Type of rims (mounted)	Aluminium
Fueltype:	Petrol	Parking lot	1062
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	No		

Options

Number of keys total	2	Lining leather
GPS		Rear parking sensors
Autom climate control		
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	205 / 60 / 17 / 97 / W / Aluminium	5,2 mm	Bridgestone	Summer
	Right	205 / 60 / 17 / 97 / W / Aluminium	4,2 mm	Bridgestone	Summer
Rear	Left	205 / 60 / 17 / 97 / W / Aluminium	6,0 mm	Hankook	Summer
	Right	205 / 60 / 17 / 97 / W / Aluminium	6,0 mm	Hankook	Summer

Assistance equipment

Interior, Dirty, Cleaning



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Windscreen, Stone chip(s), Windscreen repair



Bumper moulding FR, Scratch(es), Replace and paint



Wing RR, Dent(s), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Bodywork, Paint measurement, Acceptable



Kenteken	T171JN
Merk Model	BMW 218iA 100kW Active Tourer
Brandstofsoort	Benzine
Datum deel1	30-06-23

Datum reparatie	Kilometerstand	Reparatie omschrijving
30-04-26	151.789	Olie service
30-04-26	151.789	Onderhoudsbeurt
30-04-26	151.789	Remvloeistof
27-01-26	136.282	Bougie
29-10-25	121.338	Luchtfilter
29-10-25	121.338	Olie service
29-10-25	121.338	Onderhoudsbeurt
29-10-25	121.338	Sleutelbatterij
20-03-25	75.000	Olie service
20-03-25	75.000	Remblokken voorzijde
12-11-24	58.841	Bougie
12-11-24	58.841	Luchtfilter
12-11-24	58.841	Olie service
12-11-24	58.841	Onderhoudsbeurt
12-11-24	58.841	Ruitenwisserblad(en) voorzijde
09-04-24	29.370	Olie service
28-12-23	17.334	Reparatie band(en)