



IDENTIFICATION VEHICLE

Driver name:
Make: BMW
Model / version: IX
Vin: WBY11CF040CM07794
Plate:
Mileage: 85760
SOH: 12 %
First registration: 11/01/2023
Color: SAPPHIRE BLA


ADDITIONAL INFORMATION




Category:
Transmission:
Interior color:
Metallic paint: ?
Type of lining:
Board computer reset: ?

DOCUMENTS

Certificate of conformity: ✓
Registration certificate: ✓
Registration certificate 2: ✓
Insurance certificate: ✗
Maintenance book:
Number of keys: 2
Original key: ✓

PICTURES





VIN INFORMATION

depuis 07.22
 BMW Iconic Sounds Electric
 filet de séparation coffre
 vitrage ar avec protection solaire
 système d'appel d'urgence légal
 protection des piétons active
 indicateur de pression des pneus

liquide de climatisation R1234YF
 tuner DAB
 Design intérieur Atelier
 protection acoustique des piétons
 attache-remorque pivotant
 235/60 R 20 .. H
 spécifique Europe

climatisation automatique à 4 zones
 chargeur sans fil
 sièges av chauffants
 câble de charge monophasé Mode 3
 électrique 240 kW
 8,5 J x 20 Alu frozen midnight unie
 2 couches métallisée

EQUIPMENT

Board computer: ?
 Compressor: X
 Gps: ?
 Rear parking sensor: ?
 Front seats heated: ?
 Electric windows: ?

Central locking: ?
 Cruise control: ?
 Power steering: ?
 Repair kit: X
 Steering wheel: ?
 Climate control type: ?

Headlighting type:

Charging cables:

2

Tow bar type:

Fast charging cables:

1

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm	Goodyear	235/60/R20//108H	Winter	Aluminium	×
Front right	5 mm	Goodyear	235/60/R20//108H	Winter	Aluminium	×
Rear left	5 mm	Goodyear	235/60/R20//108H	Winter	Aluminium	×
Rear right	5 mm	Goodyear	235/60/R20//108H	Winter	Aluminium	×

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Boot lid covering R	Dirty
2	Alloy rim FL	Dent(s) and scratch(es)
3	Bumper R	Dent(s) and scratch(es)
4	Tailgate / Boot	Dent(s) and scratch(es)
5	Bumper trim R	Scratch(es)
7	Door FR	Dent(s)
8	Air vent RM	Forced
9	Fuel	Missing

Total: 8

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
6	Bodywork	Dent(s) and scratch(es)	✓	×	×

Total: 1

DAMAGES DETAILS

1 - Boot lid covering R - Dirty



2 - Alloy rim FL - Dent(s) and scratch(es)



3 - Bumper R - Dent(s) and scratch(es)



4 - Tailgate / Boot - Dent(s) and scratch(es)



5 - Bumper trim R - Scratch(es)



7 - Door FR - Dent(s)



8 - Air vent RM - Forced



9 - Fuel - Missing



6 - Bodywork - Dent(s) and scratch(es) - Renta®





SIGNATURE

Expert

03/08/2026 11:50