



RENAULT ARKANA: 7602-MDB

| | | | |
|------------------------------------|--------------------------|-------------------------|---|
| Vinnumber: | VF1RJL000UC369904 | Versionname: | Intens E-TECH Híbrido 105kW(145CV) todoterreno |
| First Registrationdate: | 28/12/2022 | Fiscalpower: | 107kW 5P automática |
| Expertise Mileage: | 157933 | Power Kw: | |
| Bodytype: | SUV | Body colour: | Blue |
| Gearbox: | Automatic | Type of rims (mounted): | Aluminium |
| Transmission: | | | |
| Fueltype: | Hybrid | | |
| Engine functioning: | Yes | | |
| Battery functioning: | Yes | | |
| Vehicle running: | Yes | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Type of rims (mounted): | Aluminium | | |
| Certificate of Conformity: | Yes | | |
| Category: | Passenger Car | | |
| Registration Certificate Car (BE): | No | | |

Options

| | | |
|--------------------------------|------------------------------|----------------------|
| Number of keys total | 2 | Central consol F |
| Number keys remote | 2 | Luggage cover |
| Windows electric F | | Rear parking sensors |
| Windows electric R | | |
| Cruise Control | | |
| Steering wheel multifunctional | | |
| Steering wheel leather | | |
| Radio multimedia | | |
| Type of climate control | Autom climate control | |

Tyres

| 215/60/17/96 H | | | | |
|-----------------------|-------|-----------------------|-------|-------------------------|
| Summer tyres: | Fr.L. | Goodyear: 6 mm | Fr.R. | Goodyear: 6 mm |
| | Re.L. | Goodyear: 6 mm | Re.R. | Goodyear: 6 mm |
| Tyre profile depth FL | | | | 6.0 |
| Tyre profile depth FR | | | | 6.0 |
| Tyre profile depth RL | | | | 6.0 |
| Tyre profile depth RR | | | | 6.0 |
| Tyre size FL | | | | 215/60 R 17 96 H |
| Tyre size FR | | | | 215/60 R 17 96 H |
| Tyre size RL | | | | 215/60 R 17 96 H |
| Tyre size RR | | | | 215/60 R 17 96 H |
| Tyre type FL | | | | Summer |
| Tyre type FR | | | | Summer |
| Tyre type RL | | | | Summer |
| Tyre type RR | | | | Summer |
| Tyre make FL | | | | 259 |
| Tyre make FR | | | | 259 |
| Tyre make RL | | | | 259 |
| Tyre make RR | | | | 259 |


Assistance equipment

| | |
|------------|------------|
| Repair kit | Yes |
|------------|------------|

Registration document, Missing, Repair/replace (lump sum)



Door FL, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing L, Scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Bonnet, Dent(s), Repair and paint (complete)



Bumper moulding FM, Scratch(es), Repair and paint (complete)



Bumper trim F, Scratch(es), Replace



Windscreen, Stone chip(s), Forfeit



Door RR, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Bumper moulding RM, Scratch(es), Repair and paint (complete)



Spoiler R, Scratch(es), Paint



Tyres, No damage, Check

