MACADAM








FORD Mondeo: 4380-LRX

Vinnumber:	**WF0FXXWPCFMR35404**	Versionname:	**2.0 TDCi 140kW Vignale PowerShift AWD SB familiar 140kW 5P automática**
First Registrationdate:	**19/07/2021**	Fiscalpower:	
Expertise Mileage:	**182022**	Power Kw:	
Bodytype:	**Berline**	Body colour	**Grey**
Gearbox:	**Automatic**	Type of rims (mounted)	**Aluminium**
Transmission:			
Fueltype:	**Diesel**		
Engine functioning	**Yes**		
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**No**		

Options

Number of keys total	**2**	Seats electric F L	
Number keys remote	**2**	Seats electric F R	
GPS big screen color		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Headlight sprinkler	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Steering wheel leather		Roof bar alu	
Seats F heated			
Radio multimedia			
Type of climate control	**Autom climate control**		

Tyres

Summer tyres:	**235/45/18/98 Y**			
	Fr.L.	**Goodyear: 0 mm**	Fr.R.	**Goodyear: 0 mm**
	Re.L.	**Goodyear: 0 mm**	Re.R.	**Goodyear: 0 mm**

Tyre size FL	**235/45 R 18 98 Y**
Tyre size FR	**235/45 R 18 98 Y**
Tyre size RL	**235/45 R 18 98 Y**
Tyre size RR	**235/45 R 18 98 Y**
Tyre make FL	**259**
Tyre make FR	**259**
Tyre make RL	**259**
Tyre make RR	**259**

Assistance equipment

Spare wheel	**Yes**	Jack	**Yes**

Interior, Dirty, Cleaning







Registration document, Missing, Repair/replace (lump sum)




Alloy rim RL, Scratch(es), Repair/replace (lump sum)




Door RL, Scratch(es), Repair and paint (complete)





Door FL, Scratch(es), Repair and paint (complete)




Wing FL, Scratch(es), Repair and paint (complete)




Alloy rim FL, Scratch(es), Repair/replace (lump sum)




Bumper F, Scratch(es), Repair and paint (complete)





Bonnet, Scratch(es), Repair and paint (complete)




Alloy rim FR, Scratch(es), Repair/replace (lump sum)




Wing FR, Scratch(es), Repair and paint (complete)




Door FR, Scratch(es), Repair and paint (complete)




Door RR, Dent(s) and scratch(es), Repair and paint (complete)




Alloy rim RR, Scratch(es), Repair/replace (lump sum)




Bumper R, Scratch(es), Repair and paint (complete)





Reflector, Broken, Replace




Tyres, No damage, Check










ALPHABET

Datos del vehículo

Marca	FORD	Matrícula	4380-LRX
Modelo	Mondeo	VIN	WF0FXXWPCFMR35404
Versión	2.0 TDCi 140kW Vignale PowerShift AWD SB familiar 140kW 5P automática		

Histórico

Fecha	Descripción	Kilómetros	Taller
03/02/2022	Revisión 1 año	21387	Kiauto Motor, S.L.
08/11/2022	Sustitución	54759	Audi Center Madrid Norte
15/12/2022	Rev. 60.000 kms	56742	DEALER Y SERVICIO POST-VENTA S.A.
04/05/2023	Puerta trasera izquierda, Techo auto, Piloto derecho	71133	Talleres Madrid
14/06/2023	Puerta trasera izquierda, Techo auto, Piloto derecho	71133	Talleres Madrid
07/06/2023	Pastillas delanteras	75986	DEALER Y SERVICIO POST-VENTA S.A.
07/11/2023	Luna parabrisas	90018	RALARSA HOLDING S.L.
08/11/2023	Rev. 90.000 kms	90061	DEALER Y SERVICIO POST-VENTA S.A.
16/09/2024	Alineado, Sustitución	111496	ANTONIO ANGEL SANCHEZ POZUELO
19/09/2024	Rev. 120.000 kms, varios	111622	MOTORAUTO LEGANES S.A.
03/01/2025	Discos traseros, Escobillas Limpiaparabrisas, Pastillas delanteras	125845	MOTORAUTO LEGANES S.A.
31/01/2025	, Techo(solar)	130858	CARROCERIAS NUEVO FENIX S.L
24/02/2025	, Techo(solar)	130858	CARROCERIAS NUEVO FENIX S.L

Fecha	Descripción	Kilómetros	Taller
28/05/2025	Rev. 150.000 kms	142460	MOTORAUTO LEGANES S.A.
10/06/2025	Alineado sencillo, Ecotasa - N2, Goodyear / 235/45R18 98Y EAG F1 ASY 6 XL FP, Sustitucion y kit de montaje	143424	TALLERES VILLANUEVA Y NEUMATICOS S.L.
23/06/2025	Paragolpes trasero, sensores aparcamiento	143432	CARROCERIAS NUEVO FENIX S.L
18/06/2025	Paragolpes trasero, sensores aparcamiento	143432	CARROCERIAS NUEVO FENIX S.L
11/02/2026	Aceite motor - - - APL 13, Arandela / tapón cárter, Filtro aceite, Filtro aire, Filtro antipolen - Nueva, Filtro combustible, Serv inspección 180000 KM, Tasa de gestión de aceites usados	171270	MOTORAUTO LEGANES S.A.
12/05/2026	Ecotasa - N2, Goodyear / 235/45R18 98Y EAG F1 ASY 6 XL FP, Sustitucion y kit de montaje	177609	LAVADO Y ENGRASE QUINTANA S.L.