



Expertise

Protocol number: 46888054
Order No. / Reference: 26751064
Inspection date: 5 Aug 2026

Manufacturer: SMART

Model: fortwo coupe EQ

VIN: W1A4533911K475882



Vehicle details	
Manufacturer / Type / Model / Equipment	
SMART fortwo coupe EQ	
Vehicle Identification number	W1A4533911K475882
Mileage (Read)	14,708 km
First registration	25 Apr 2022
Number of holders	1
Fuel type	Electric
Power	41 kW
Gearbox / Number of gears	Direct drive / 1
Type of drive	Rear drive
Type of vehicle	Saloon car
Colour / colour code	White
Doors / Seats	3 / 2
Upholstery type	Cloth
Colour of upholstery	Black
Vehicle with smoke odor	no



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	20,000 km
Last service on / at	07/2024 at 10,817 km		
Key is / should be	1 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ441423
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	2222 / ADL 00034		
Emission standard	2017/1151	fine dust sticker	
Permitted total weight	1,310 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	165/65 R15 81T	All-season tyres on Light alloy	Goodyear	4mm / 4mm
2)	185/60 R15 84T	All-season tyres on Light alloy	Goodyear	5mm / 5mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Equipment

- Klimaautomatik

Standard equipment

- | | |
|---|--|
| <ul style="list-style-type: none"> • Storage compartment in the doors • Airbag: Kneebag for driver • Airbag: Windowbags for driver and front passenger • Anti-lock braking system (ABS) • Outdoor temperature display • Brake assist active • Third brake light in LED technology • Electronic Stability Program (ESP) • Transmission: 1-speed • Glove compartment, open • Back window, heater • Interior lighting • Instrument cluster with monochrome LCD display and on-board computer • Front headrests • Headlight range control • Center console with roller blind • Upholstery: Cloth • Tire pressure monitoring system • Crosswind Assist • Seat belts • Seats: i-Size child seat attachment on the front passenger seat • Cruise control with limiter • Central locking with remote control and immobilizer | <ul style="list-style-type: none"> • Driver and passenger side airbags • Airbag: Sidebags for driver and front passenger • Acoustic environmental protection • Exterior mirrors manually adjustable • Hill start assist • Roof: Full roof with black fabric covering • Drive Lock • electric window regulator • H4 halogen headlights with integrated LED daytime running lights • rear window wiper • Black grained instrument panel with black fabric door center panels and black accent pieces. • Comfort windscreen wipers • Charging cable (smooth, 5 m) for wallbox and public charging stations • Package: Cool & Audio • Radio: Digital Radio (DAB) • Leather gear knob • Electric power steering • Seats: Passenger seat with pass-through function • smart EQ control app • 12-volt socket with cover • TRIDION - Security cell black (uni) • Additional instruments (battery charge level and power indicator) |
|---|--|

Extra equipment

- | | |
|--|---|
| <ul style="list-style-type: none"> • 22 kW on-board charger with fast charging function • Velour floor mats (black) • Package: Plus (for base model) (38.1 cm (15") alloy wheels in 4-twin-spoke design with tires front axle 165/65 R 15 on 5J x 15, rear axle 185/60 R 15 on 5.5J x 15 - Height-adjustable driver's seat - One-touch backrest adjustment for driver and front passenger - Height-adjustable steering column - Electrically adjustable and heated exterior mirrors - Electric windows with comfort operation and anti-pinch protection - Lockable glove compartment - Load compartment cover (roller blind) with net pocket - Tire repair kit with air compressor and sealant) | <ul style="list-style-type: none"> • Body panels white (uni) • Package: advanced (smart Media-System connect (high-resolution 20.2 cm (8") multi-touch display, Apple CarPlay, Android Auto, Bluetooth, hands-free system, 2 USB Type-A, 1 AUX) - smartphone integration - center console with roller blind and front center armrest (foldable) - rear parking aid with acoustic warning) • Wheels: All-season tires instead of summer tires (front tires 165/65 R 15, rear tires 185/60 R 15) • Wheels: 38.1 cm (15") light alloy wheels in a 4-twin-spoke design (with tires front 5Jx15 / 165/65 R 15, rear 5.5Jx15 / 185/60 R 15) |
|--|---|



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Side panel - rear right side	Side panel - dent(s) - Smooth repair work
2	Body	Body - Glued / labelled - De-glue / neutralise
3	Front bumper	Front bumper - Scratched - Paint

Wear and tear

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Vehicle glazing	Windscreen - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Equipment - Vehicle key with remote control

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents



Figure 15: Misc.



Figure 16: Misc.




Figure 17: Misc.



Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Damage 1: Side panel - rear right side: Side panel - dent(s) - Smooth repair work



Damage 1: Side panel - rear right side: Side panel - dent(s) - Smooth repair work



Damage 2: Body: Body - Glued / labelled - De-glue / neutralise



Damage 2: Body: Body - Glued / labelled - De-glue / neutralise



Damage 2: Body: Body - Glued / labelled - De-glue / neutralise



Damage 2: Body: Body - Glued / labelled - De-glue / neutralise



Damage 3: Front bumper: Front bumper - Scratched - Paint



Damage 3: Front bumper: Front bumper - Scratched - Paint



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W1A4533911K475882
Hersteller / Modell: SMART SMART smart fortwo coupe EQ

Datum	KM-Stand	Beschreibung
10.07.2024	10.817	Regelwartungsdienst
01.06.2023	6.689	Regelwartungsdienst